

23 GREEN VILLAGE RD. MADISON NJ 07940

COMMENTS:

November 9, 2017

#### TRANSMITTAL

TO: CITY OF PORTLAND

**BUREAU OF DEVELOPMENT SERVICES** 

ATTN: CHENG-MIN PAO

1900 SW FOUTH AVENUE, SUITE 5000

PORTLAND, OREGON 97201

RE: ASA PROJECT #17051

SPECIAL INSPECTION REPORT

LOFT OUTLET STORE CASCADE STATION SPACE #MAJOR C

ENCLOSED:

#OF COPIES	DWG NO.	DATE	DESCRIPTION
2		11/09/17	COPIES OF THE SPECIAL INSPECTION REPORT

# \*\*NOTES:

PLEASE FIND A HARD COPY OF THE SPECIAL INSPECTION REPORT FOR PERMIT #17-188501-000-00-CO (JOB #17-7602)

CONTACT:

ROXANNA SCOTTO PROJECT MANAGER

RSCOTTO@GROUPASA.COM

T: 973.377.1313 X 128

F: 973.377.1562

ASA RETAIL STUDIO. COM

17-188501-CO [SCAN]



## SPECIAL INSPECTION REPORT

ACS Testing, Inc 7409 SW Tech Center Dr., Suite 145 Tigard, OR 97223

Phone: 503-443-3799 Fax: 503-620-2748

Job#

17-7602

Date: Nov 8, 2017

Permit # 17-188501-000-00-CO

Mail To:

MANAGEMENT RESOURCE 1907 BAKER RD. HIGH POINT, NC 27263 Project:

LOFT OUTLET 9971 NE CASCADE PKWY PORTLAND, OR 97220

Inspector: Jerry Frampton Cert# OBOA 859

### Field Inspection:

ACS representative on site for inspection of new bracing attachment connections. With the existing conditions the contractor has used detail 1/A10.41 in lieu of detail 2/A10.41. The completed bracing attachments are acceptable per the mentioned detail. No issues noted.

Our reports pertain to the material tested or inspected only. Information contained herein is not to be reproduced except in full, without prior written authorization from this office.

Reviewed:

Bostarone

Date: Nov 8, 2017

BB/jf

CC:

TRAVIS JARRETT, JASON BOOKHEIMER



#### SPECIAL INSPECTION REPORT

Date: Nov 8, 2017

ACS Testing, Inc 7409 SW Tech Center Dr., Suite 145

Tigard, OR 97223

Phone: 503-443-3799 Fax: 503-620-2748

Job#

17-7602

Permit # 17-188501-000-00-CO

Mail	To
IVIAII	1 ()

MANAGEMENT RESOURCE 1907 BAKER RD. HIGH POINT, NC 27263 Project:

LOFT OUTLET 9971 NE CASCADE PKWY PORTLAND, OR 97220

Inspector: Jerry Frampton Cert# OBOA 859

#### Field Inspection:

ACS representative on site for inspection of new bracing attachment connections. With the existing conditions the contractor has used detail 1/A10.41 in lieu of detail 2/A10.41. The completed bracing attachments are acceptable per the mentioned detail. No issues noted.

Our reports pertain to the material tested or inspected only. Information contained herein is not to be reproduced except in full, without prior written authorization from this office.

Reviewed:

Bosterone

Date: Nov 8, 2017

BB/jf

CC:

TRAVIS JARRETT, JASON BOOKHEIMER