

Pacwest Center Building repositioning


DESIGN ADVICE REVIEW 01.29.2016

VICINITY STUDY







EXISTING CONDITIONS




- 1. Lack of main entry identity. Limited visibility to interior atrium
- 2. Planter acts as an obstacle between pedestrians and building
- 3. Retail storefronts lack engagement with pedestrians




- 1. Lack of main entry identity. Limited visibility to interior atrium
- 2. Planter acts as an obstacle between pedestrians and building
- 3. Retail storefronts lack engagement with pedestrians




- 1. Underutilized terraces serve as obstacles rather than connections betweens tenants and pedestrians
- 2. Canopies distract rather than enhance retail identity



- 1. Retail storefronts and entries have no visual connection to pedestrians
- 2. Canopies distract rather than enhance retail identity
- 3. Large canopy is a visual barrier to the building's entry, lacks distinction as the primary entry to the building
- 4. Open area is undefined and underutilized



- 1. No sense of primary building entry
- 2. Canopies distract rather than enhance retail identity



- 1. Planters serve as visual and physical barriers between pedestrians and tenants
- 2. Planters provide limited seating opportunity due to wide variation in heights




GOALS

G	en	s	eı
	~ .	_	

- CREATE A STRONGER CONNECTION BETWEEN THE PEDESTRIAN AND PACWEST
- ESTABLISH A VIBRANT RETAIL ENVIRONMENT TO ENLIVEN THE NEIGHBORHOOD
- PRESERVE AND ENHANCE PACWEST'S ICONIC DESIGN

DESIGN APPROACH




Legend


- 1. Raised Steel Planter with Signage
- 2. Wood Slab Bench
- 3. Bermed Entry Feature Planting Area
- 4. Specialty Concrete Paving to Match Lobby Paving
- 5. Flush Paving Entry To Starbucks Area
- 6. Raised Steel Planter with Bench
- 7. Light Rail Canopy
- 8. Bermed Entry Feature Planter
- 9. Sidewalk Level Planters
- 10. Secondary Entry Paving Stone Pavers
- 11. Property Line


$\overline{\bigcirc}$ 0 (15) 2 -(3) \bigcirc \bigcirc 4 <u></u> -(5) \bigcirc 14 6 \bigcirc 13 \bigcirc \bigcirc 7 \bigcirc -(8) \bigcirc 12 9 0 \bigcirc 0 11) \circ \circ

Legend

- 1. Inlet, Typical
- Existing Terrace to be Removed
 Replaced
- 3. Property Line
- 4. Existing Trees to Remain, Typical
- 5. Street Level Glazing to be Replaced
- 6. New Entrance Canopy
- 7. Existing Planter to be Removed
- 8. Existing Rooftop Garden to be Renovated
- 9. Water Connection & Meter Vault
- 10. Water Connection
- 11. Water Main
- 12. New Enclosure Under Existing Building Soffit
- 13. Existing Planters to be Removed & Reworked, Typical
- 14. Existing Trees within Property to be Removed & Replaced,
 Typical
- 15. Existing Canopy to be Removed & Reworked, Typical





















































































APPENDIX



NIC - CORE	
NIC	
CIRCULATION	
TENANT	0 SF
RETAIL	12,515 SF
CONFERENCE	0 SF
SEATING	1,100 SF
 INFORMAL GATHERING	0 SF
AMENITY	0 SF
LEASABLE STORAGE	







