




Burlingame Tanks Improvements Project

City Council Presentation

David Shaff
Administrator
July 13, 2011



Interior Condition of Tank 4 During 2005 Evaluation – Paint is Failing



Burlingame Tanks Improvements Project

Interior Condition of Tank 4 During 2010 Construction



Paint failed and steel deteriorating

Steel at roof connection is corroded and unsound



Tank 4 Roof Removal



Side walls will be removed separately

Burlingame Tanks Improvements Project

Exterior Condition of Tank 3 During 2010 Construction



***Steel at top connection
unsound***

***Hole in sidewall with
screwdriver stuck through***



Exterior Spot Treatment



Purple areas are the spot treatment



Spot treatment area is greater than 15%

Burlingame Tanks Improvements Project

Final Condition of Tanks



Condition of tanks markedly improved

Burlingame Tanks Improvements Project