





## City of Portland, Oregon - Bureau of Development Services



1900 SW Fourth Avenue Portland, Oregon 97201 | 503-823-7300 | www.portlandoregon.gov/bds

## **Permit Revision Submittal Requirements and Application**

A Permit Revision is required when there are proposed changes to the project after the permit has been issued. This may arise due to discrepancies between the city-approved permit drawings and actual field conditions, or the customer has changed their mind about an aspect of the project. In all cases, a revision to the existing permit must be submitted, reviewed and approved.

Applicants will provide:	One (1) copy of the original city approved permit
A copy of this application	drawings. (NOTE: If your project has an assigned process
Three (3) sets of plans that clearly reflect the propos	ed Two (2) sets of calculations, if applicable
change(s).	Two (2) sets of calculations, if applicable
Drawings and calculations must be stamped and sig	Inspector's correction notice, if revision is due to
by the Architect and/or the Engineer of Record, if	an inspection correction
applicable.	Revision fee (paid at time of submittal)
Contact Information:	
Contact name Carissa Page / Matti	Sjoblom
Address 7035 N. Fairport Pl.	
	te OR Zip Code 97217
Phone 202-486-7513 Em	ail carissa_page@hotmail.com
Value of proposed revision 0	Issued permit # 17 - 117 754 - RS.
Job site address 7050 N. Mississin	Pi AVP
Description of revision Sewer from house to ADU to be installed via trenching rather than directional drilling	
Fees:	
The Permit Revisions are subject to fees associated with plan review, processing and any increase in project value. Additional fees may apply if adding plumbing fixtures.	
The Bureau of Development Services fee schedule is available under the fees tab on the BDS web site at: www.portlandoregon.gov/bds. Fees are updated annually on July 1st.	
Helpful Information:	Important Telephone Numbers:
<b>Bureau of Development Services</b>	BDS main number503-823-7300
City of Portland, Oregon 1900 SW 4th Avenue, Portland, OR 97201 www.portlandoregon.gov/bds	DSC automated information line503-823-7310
	Building code information503-823-1456
Submit your plane in person to	BDS 24 hour inspection request line503-823-7000
Submit your plans in person to:	Residential information for
Development Services Center (DSC), First Floor, For Hours Call 503-823-7310	one and two family dwelling503-823-7388
	General Permit Processing and Fee Estimate info
	City of Portland TTY503-823-6868

## **HARRITY**

TREE SPECIALISTS, INC. PO BOX 12395
PORTLAND, OR 97212
503-331-0452
harritytree@comcast.net

MATTHEW SANCHEZ
CERTIFIED ARBORIST

Attn: Carissa Page

Performance Path Tree Protection Plan

Site location: 7035 N. Fairport Pl Portland, OR

Arborist: Matthew Sanchez, ISA Certified Arborist PN 7830A

Site Visit: 1:00 p.m. 02/16/2017

A Prescriptive path is not practicable because the size of this trees DBH would make it impossible to perform work on this site. There is a garage in the way of a prescriptive path and the machinery needed to trench the sewer line would not be able to fully move in the yard.

Tree Information

## Tree 1

a. 30" Douglas fir located on the SE side of the garage. The root cover is presumably the extent of the dripline. The dripline extends past the property line. Upon observation of the soil and foundation of the garage there appears to be no swelling or surface roots.

b. The trees tolerance to construction is good assuming that all protective measures are taken during activity on site. Douglas fir can have root pruning on the outer reach of their dripline and still maintain their stability. This tree is very healthy and should have no issue with work around it.

c. There have been a few impacts to the root zone but nothing significant enough to display negative consequences.

a. The garage footings may have impacted the roots, but there is no sign of swelling or severed roots.

b. There is a rain garden near the base of the tree, this simply changed the hydrology of the root zone but did not negatively impact its health.

Providing

KNOWLEDGEABLE

PNW/ ISA #7830A CCB #84426

CARE FOR TREES

IN THE URBAN

ENVIRONMENT

Tree 2

- a. 15" Mountain ash is located about 15' NE of the Douglas fir. This tree is considered a nuisance species and is technically exempt from protection. I have no concern of the roots of this tree being impacted by sewer excavation.
- b. The trees tolerance to construction is fair. This tree is healthy for its age and species and should have no issue with work around it.
- c. There are no visible impacts to this tree in the past.

Tree 3

a. 22" Douglas fir located on the far west section of the property. This tree will be protected by the fence around tree 1&2 and will have zero potential for impact. I have noted this tree on here to reinforce that it will be protected.

**Front Trees** 

a. There is a 11" southern magnolia, port orford cedar, and Japanese maple. All of these trees are out of the direct work area and are further protected by a 6' landscape fence.

The Alternate Tree Protection Plan will be a reduced tree protection fence. The fence will be connected to the garage and deck. The fence will be 15' across protecting the fir tree. Regular tree protection standards for fencing apply to this project (6' chain link fence with 8' posts). There are no alternate construction techniques that Harrity Tree Specialists, INC. can suggest that will further protect the trees on site. The alternative method will adequately protect the trees by protecting a significant amount of root cover and restricting access to the trunks from damage.

There is no requirement for an arborist to be on site for this project.