Park Cept

Cark Cept

May 26, 1931.

Mr. L. S. Kaiser, Sup't, Bureau of Water Works, City Hall.

Re: Public Cymnasium, 82nd & E. Glisan Sts.

Dear Sir:

A recent inspection of the premises located as above was made by Inspector Greene of this office, who reports that children deposit papers and other trash in space between the inside and outside walls of this building.

It appears that this trash cannot be removed, and it is recommended that spaced be closed at top, as a match or eigerette in this debris might start a serious fire.

It also seems advisable to furnish some kind of fire protection for this building. A standpipe and sufficient one-and one-half $(\frac{1}{2})$ inch hose to reach all parts of the building is recommended.

We thank you for your past cooperation and trust you will give these recommendations your immediate attention.

Yours very truly,

FIRE MARSHAL.

FWR: WRF GREENE: INSP:

Repartment.

Jamuary 9, 1931

Mr. M. O'Dell, Superintendent of Properties, School District #1, 7th & Clackamas Streets, City

> In re: Vestal School 75 E. 82nd Street N.

Dear Sir:

A Fire Prevention survey was recently made of the Vestal School by Inspector Close from this office, and he reports the following unsatisfactory conditions which are called to your attention:

Cabinets containing fire hose are not marked. These cabinets should be letter "Fire Hose" with two inch red letters.

No fire extinguishers have been provided for this building. Fire extinguishers should be installed in the following rooms:

the following rooms:

Kitchen, Domestic Science, Manual Training, Boiler
Room, and Motion Pictur Booth.

Excessive amounts of paint and volatile liquids found in Manual Training Room. An approved metal cabienet of 50 gallon capacity should be provided for the storage of this material.

Combustible material back of drop curtain on rear of stage should be removed.

Thanking you for your past cooperation and trusting you will give the above conditions your attention, I am

Yours very truly,

FIRE MARSHAL

INSP: CLOSE FWR:RH April 11, 1931.

Mr. M. O'Dell, Sup't of Properties, School Dist: No.1., 7th and Clackamas Sts, City.

Dear Sir:

Fire Prevention surveys have recently been made of the Vestal and Llewellyn Schools, and the following ordinance violations and unsefe fire conditions were noted and are called to your attention for correction:-

At the Vestal school it was noted that the foam fire extinguisher for fire protection in boiler room, recommended at time of last inspection, had not yet been installed.

At the Llewellyn school the inspector reports that fire door in wall between boiler room and playroom is not equipped with a self-closing device as required by Section 498, Ordinance No. 53911.

Very thuly yours

FIRE MARSHAL.

FWR: WRF GALLAHER CLOSE: INSP: