

### **OVERVIEW**

| C.6  | Zoning Map and Site Photos    |
|------|-------------------------------|
| C.7  | Original Building Photo       |
| C.8  | Site Survey/ ROW Improvements |
| C.9  | Site Diagram                  |
| C.10 | Site Sections and Zoning Data |
| C.11 | Enlarged Sections             |

### **PROJECT**

| C.12 | Basement Floor Plan                 |
|------|-------------------------------------|
| C.13 | Site and First Floor Plan           |
| C.14 | Typ 2-5 Floor Plan                  |
| C.15 | 6th Floor Plan                      |
| C.16 | Roof Plan                           |
| C.17 | North Elevation                     |
| C.18 | West Elevation                      |
| C.19 | South Elevation                     |
| C.20 | East Elevation                      |
| C.21 | Rendering                           |
| C.22 | Rendering                           |
| C.23 | Rendering                           |
| C.24 | Rendering                           |
| C.25 | Rendering                           |
| C.26 | Aerial Rendering                    |
| C.27 | Parking Screen Renderings           |
| C.28 | Parking Screen Elevations           |
| C.29 | Parking Screen Sections and Details |
| C.30 | Rendering                           |
| C.31 | Rendering                           |
| C.32 | Rendering                           |
| C.33 | Rendering                           |
|      |                                     |

### **APPENDIX**

| C.36 | Materials          |
|------|--------------------|
| C.37 | Screen Precedents  |
| C.38 | Trellis Precedents |
| C.39 | Landscape Concepts |
| C.40 | Landscape Concepts |

**INFORMATION** 

LU#: EA 13-232583 DA PROPERTY: 1021 NE Grand Ave Portland, OR 97219

Design Advice Request RE: January 24, 2014 ORIGINALLY SUBMITTED:

ARCHITECT: Holst Architecture CONTACT: Kevin Valk, Project Manager kvalk@holstarc.com

503 233 9856

LANDSCAPE: Lango Hansen CONTACT: Jane Hansen, Principal

jane@langohansen.com 503 295 2437

CIVIL: **KPFF Consulting Engineers** CONTACT: Mark Reuland

mark.reuland@kpffcivilpdx.com 503 542 3827

OWNER: Grand Ventures Hotel, LLC CONTACT: Desmond Mollendor, Owner dmollendor@gmail.com

503 970 2055

| C.6  | Original Building Photo       |
|------|-------------------------------|
| C.7  | Zoning Map and Site Photos    |
| C.8  | Site Survey                   |
| C.9  | Site Diagram                  |
| C.10 | Site Sections and Zoning Data |
| C.11 | Enlarged Sections             |
|      |                               |

# OVERVIEW

ORIGINAL BUILDING PHOTO

Shee

C.6



Photo of Original Building Design - 1963

DESIGN **ADVICE** REQUEST 01.24.2014

EA 13--232583 DA

**ZONING MAP** AND SITE **PHOTOS** 

**C.7** 



1. View from NE Holladay and NE Grand Ave



2. View from Parking Deck






4. View from NE Hassalo and NE MLK Jr Blvd



5. View from NE Hassalo St







6. View from NE Grand Ave

**Zoning Map** 

SITE SURVEY ROW IMPRO-

**VEMENTS** 





RED LION HOTEL REMODEL

DESIGN ADVICE REQUEST

01.24.2014

EA 13--232583 DA

SITE DIAGRAM

Title:

Sheet

### DESIGN ADVICE REQUEST 01.24.2014

01.24.2014

EA 13--232583 DA

Title:

SITE SECTIONS AND ZONING DATA

Sheet:

### **BUILDING REMODEL**

Building Area 125,675 SF Height Limit 250'-0" Height 74'-0"

Building Use 34,807 Gross Square Feet of S-2 (Parking)

1,267 Gross Square Feet of B (Office)

12,067 Gross Square Feet of A-2 (Restaurant and Banquet Hall)

77,567 Gross Square Feet of R-1 (Hotel)

Bike Parking Short Term: 12 required, 12 provided

Long Term: 11 required, 11 provided


Vehicle Parking 124 Parking Stalls


4 ADA Parking Stalls


1 ADA Van Accessible Stall

FAR Building = 125,675 SF

Lot = 38,000 SF FAR = 3.3:1







| C.12 | Basement Floor Plan                 |
|------|-------------------------------------|
| C.13 | Site and First Floor Plan           |
| C.14 | Typ 2-5 Floor Plan                  |
| C.15 | 6th Floor Plan                      |
| C.16 | Roof Plan                           |
| C.17 | North Elevation                     |
| C.18 | West Elevation                      |
| C.19 | South Elevation                     |
| C.20 | East Elevation                      |
| C.21 | Rendering                           |
| C.22 | Rendering                           |
| C.23 | Rendering                           |
| C.24 | Rendering                           |
| C.25 | Rendering                           |
| C.26 | Aerial Rendering                    |
| C.27 | Parking Screen Renderings           |
| C.28 | Parking Screen Elevations           |
| C.29 | Parking Screen Sections and Details |
| C.30 | Rendering                           |
| C.31 | Rendering                           |
| C.32 | Rendering                           |
| C 33 | Dandaring                           |

# PROJECT

Holst Architecture


01.24.2014 EA 13--232583 DA

BASEMENT FLOOR PLAN

Floor Plan at Basement Level








SITE AND FIRST FLOOR

She




Holst Architecture

01.24.2014

EA 13--232583 DA

TYP 2-5 FLOOR PLAN




Floor Plan at Levels 2-5 (Typical Guest Room Floor)



6TH FLOOR PLAN

Shee




01.24.2014

EA 13--232583 DA

Title

**ROOF PLAN** 

Sheet



01.24.2014 EA 13--232583 DA

Title

NORTH ELEVATION

ELEVATIC

Sheet

1 EXISTING BRICK PATTERN, REMOVE PAINT

(2) NEW ALUMINUM CURTAIN WALL

**KEY** 

(3) NEW ALUMINUM STOREFRONT

4 NEW CONCRETE PANEL OR METAL PANEL

(5) NEW WHITE PAINTED METAL PANEL WITH CONCEALED FASTENERS

6 NEW PERFORATED METAL SCREEN

7 NEW METAL LINEAR CEILING

8 NEW PAINTED TUBE STEEL TRELLIS

13) NEW STAIR
14) NEW STREET TREES

(15) REMOVE EXISTING SIGN

16 NEW LANDSCAPING

(17) NEW ELEVATOR




WEST ELEVATION

Sheet

<u>KEY</u>

- 1 EXISTING BRICK PATTERN, REMOVE PAINT
- 2 NEW ALUMINUM CURTAIN WALL
- (3) NEW ALUMINUM STOREFRONT
- (4) NEW CONCRETE PANEL OR METAL PANEL
- 5 NEW WHITE PAINTED METAL PANEL WITH CONCEALED FASTENERS
- 6 NEW PERFORATED METAL SCREEN
- 7 NEW METAL LINEAR CEILING
- (8) NEW PAINTED TUBE STEEL TRELLIS

- 9 NEW ROOF
- (10) NEW TRAFFIC COATING
- (11) NEW SIDEWALK
- (12) NEW ON-SITE PEDESTRIAN WALKWAY
- (13) NEW STAIR
- (14) NEW STREET TREES
- (15) REMOVE EXISTING SIGN
- (16) NEW LANDSCAPING
- (17) NEW ELEVATOR




West Elevation at NE MLK Jr Blvd



- 1 EXISTING BRICK PATTERN, REMOVE PAINT
- 2 NEW ALUMINUM CURTAIN WALL
- (3) NEW ALUMINUM STOREFRONT
- 4 NEW CONCRETE PANEL OR METAL PANEL
- (5) NEW WHITE PAINTED METAL PANEL WITH CONCEALED FASTENERS
- 6 NEW PERFORATED METAL SCREEN
- 7 NEW METAL LINEAR CEILING
- (8) NEW PAINTED TUBE STEEL TRELLIS

- 9 NEW ROOF
- (10) NEW TRAFFIC COATING
- (11) NEW SIDEWALK
- (12) NEW ON-SITE PEDESTRIAN WALKWAY
- 13) NEW STAIR
- (14) NEW STREET TREES
- (15) REMOVE EXISTING SIGN
- (16) NEW LANDSCAPING
- (17) NEW ELEVATOR




EAST ELEVATION

Shee

<u>KEY</u>

- 1 EXISTING BRICK PATTERN, REMOVE PAINT
- 2 NEW ALUMINUM CURTAIN WALL
- (3) NEW ALUMINUM STOREFRONT
- (4) NEW CONCRETE PANEL OR METAL PANEL
- 5 NEW WHITE PAINTED METAL PANEL WITH CONCEALED FASTENERS
- 6 NEW PERFORATED METAL SCREEN
- 7 NEW METAL LINEAR CEILING
- (8) NEW PAINTED TUBE STEEL TRELLIS

- 9 NEW ROOF
- (10) NEW TRAFFIC COATING
- (11) NEW SIDEWALK
- (12) NEW ON-SITE PEDESTRIAN WALKWAY
- (13) NEW STAIR
- (14) NEW STREET TREES
- (15) REMOVE EXISTING SIGN
- (16) NEW LANDSCAPING
- (17) NEW ELEVATOR





Perspective of North-East Corner at NE Grand Ave and NE Hassalo St

## **KEY**

- 1 EXISTING BRICK PATTERN, REMOVE PAINT
- (2) NEW ALUMINUM CURTAIN WALL
- (3) NEW ALUMINUM STOREFRONT
- (4) NEW CONCRETE PANEL OR METAL PANEL
- 5 NEW WHITE PAINTED METAL PANEL WITH CONCEALED FASTENERS
- (6) NEW PERFORATED METAL SCREEN
- 7 NEW METAL LINEAR CEILING
- 8 NEW PAINTED TUBE STEEL TRELLIS
- 9 NEW ROOF
- (10) NEW TRAFFIC COATING
- (11) NEW SIDEWALK
- (12) NEW ON-SITE PEDESTRIAN WALKWAY
- (13) NEW STAIR
- (14) NEW STREET TREES
- (15) REMOVE EXISTING SIGN
- (16) NEW LANDSCAPING
- (17) NEW ELEVATOR



**Existing Conditions** 

DESIGN **ADVICE** REQUEST 01.24.2014

EA 13--232583 DA

RENDERING

### DESIGN **ADVICE** REQUEST

01.24.2014

EA 13--232583 DA

RENDERING

- 1 EXISTING BRICK PATTERN, REMOVE PAINT
- (2) NEW ALUMINUM CURTAIN WALL
- (3) NEW ALUMINUM STOREFRONT
- (4) NEW CONCRETE PANEL OR METAL PANEL
- 5 NEW WHITE PAINTED METAL PANEL WITH CONCEALED FASTENERS
- (6) NEW PERFORATED METAL SCREEN
- 7 NEW METAL LINEAR CEILING
- (8) NEW PAINTED TUBE STEEL TRELLIS
- 9 NEW ROOF
- (10) NEW TRAFFIC COATING
- (11) NEW SIDEWALK
- (12) NEW ON-SITE PEDESTRIAN WALKWAY
- 13) NEW STAIR
- (14) NEW STREET TREES
- (15) REMOVE EXISTING SIGN
- (16) NEW LANDSCAPING
- (17) NEW ELEVATOR



**Existing Conditions** 



Perspective of South-East Corner at NE Grand Ave and NE Holladay St

RENDERING

- 1 EXISTING BRICK PATTERN, REMOVE PAINT
- 2 NEW ALUMINUM CURTAIN WALL
- (3) NEW ALUMINUM STOREFRONT
- (4) NEW CONCRETE PANEL OR METAL PANEL
- 5 NEW WHITE PAINTED METAL PANEL WITH CONCEALED FASTENERS
- (6) NEW PERFORATED METAL SCREEN
- 7 NEW METAL LINEAR CEILING
- 8 NEW PAINTED TUBE STEEL TRELLIS
- 9 NEW ROOF
- (10) NEW TRAFFIC COATING
- (11) NEW SIDEWALK
- (12) NEW ON-SITE PEDESTRIAN WALKWAY
- (13) NEW STAIR
- (14) NEW STREET TREES
- (15) REMOVE EXISTING SIGN
- (16) NEW LANDSCAPING
- 17) NEW ELEVATOR



Perspective of South-East Corner at NE Grand Ave and NE Holladay St

### DESIGN **ADVICE** REQUEST

01.24.2014

EA 13--232583 DA

RENDERING

- 1 EXISTING BRICK PATTERN, REMOVE PAINT
- (2) NEW ALUMINUM CURTAIN WALL
- (3) NEW ALUMINUM STOREFRONT
- (4) NEW CONCRETE PANEL OR METAL PANEL
- 5 NEW WHITE PAINTED METAL PANEL WITH CONCEALED FASTENERS
- (6) NEW PERFORATED METAL SCREEN
- 7 NEW METAL LINEAR CEILING
- (8) NEW PAINTED TUBE STEEL TRELLIS
- 9 NEW ROOF
- (10) NEW TRAFFIC COATING
- (11) NEW SIDEWALK
- (12) NEW ON-SITE PEDESTRIAN WALKWAY
- (13) NEW STAIR
- (14) NEW STREET TREES
- (15) REMOVE EXISTING SIGN
- (16) NEW LANDSCAPING
- (17) NEW ELEVATOR



**Existing Conditions** 



Perspective of North-West Corner at NE MLK Jr Blvd and NE Hassalo St



Perspective of North-West Corner at NE MLK Jr Blvd and NE Hassalo St

## **KEY**

- EXISTING BRICK PATTERN, REMOVE PAINT
- (2) NEW ALUMINUM CURTAIN WALL
- (3) NEW ALUMINUM STOREFRONT
- (4) NEW CONCRETE PANEL OR METAL PANEL
- 5 NEW WHITE PAINTED METAL PANEL WITH CONCEALED FASTENERS
- (6) NEW PERFORATED METAL SCREEN
- 7 NEW METAL LINEAR CEILING
- 8 NEW PAINTED TUBE STEEL TRELLIS
- 9 NEW ROOF
- (10) NEW TRAFFIC COATING
- (11) NEW SIDEWALK
- (12) NEW ON-SITE PEDESTRIAN WALKWAY
- (13) NEW STAIR
- (14) NEW STREET TREES
- (15) REMOVE EXISTING SIGN
- (16) NEW LANDSCAPING
- (17) NEW ELEVATOR

DESIGN **ADVICE** REQUEST

01.24.2014

EA 13--232583 DA

RENDERING

Title

RENDERING

## **KEY**

- 1 EXISTING BRICK PATTERN, REMOVE PAINT
- (2) NEW ALUMINUM CURTAIN WALL
- 3 NEW ALUMINUM STOREFRONT
- (4) NEW CONCRETE PANEL OR METAL PANEL
- 5 NEW WHITE PAINTED METAL PANEL WITH CONCEALED FASTENERS
- (6) NEW PERFORATED METAL SCREEN
- 7 NEW METAL LINEAR CEILING
- (8) NEW PAINTED TUBE STEEL TRELLIS
- 9 NEW ROOF
- (10) NEW TRAFFIC COATING
- (11) NEW SIDEWALK
- (12) NEW ON-SITE PEDESTRIAN WALKWAY
- 13) NEW STAIR
- (14) NEW STREET TREES
- (15) REMOVE EXISTING SIGN
- (16) NEW LANDSCAPING
- (17) NEW ELEVATOR



**Aerial view from the South-West** 



Perspective of South-West Corner of Lot






**South-West Corner of Parking Screen** 

# **KEY**

- EXISTING BRICK PATTERN, REMOVE PAINT
- 2 NEW ALUMINUM CURTAIN WALL
- (3) NEW ALUMINUM STOREFRONT
- (4) NEW CONCRETE PANEL OR METAL PANEL
- 5 NEW WHITE PAINTED METAL PANEL WITH CONCEALED FASTENERS
- (6) NEW PERFORATED METAL SCREEN
- 7 NEW METAL LINEAR CEILING
- 8 NEW PAINTED TUBE STEEL TRELLIS
- 9 NEW ROOF
- (10) NEW TRAFFIC COATING
- (11) NEW SIDEWALK
- (12) NEW ON-SITE PEDESTRIAN WALKWAY
- 13) NEW STAIR
- (14) NEW STREET TREES
- (15) REMOVE EXISTING SIGN
- (16) NEW LANDSCAPING
- 17) NEW ELEVATOR



**Existing Conditions** 

DESIGN ADVICE REQUEST 01.24.2014

EA 13--232583 DA

**PARKING** SCREEN

Parking Screen at NE Holladay St

### DESIGN ADVICE REQUEST

01.24.2014

EA 13--232583 DA

Title

PARKING SCREEN ELEVATIONS

Sheet:


### **OPEN PARKING AREA:**

Exterior Wall Area: 8,931sf 20% of the exterior wall area must remain open to be considered "open parking"


Required open area: 1,786sf Existing open area: 3,050sf


The proposed screening would reduce the existing open area by no more than 40%.

Proposed open area: ±1,850sf



### 1. South Screen Elevation - NE Holladay St





### DESIGN ADVICE REQUEST

01.24.2014

EA 13--232583 DA

\_\_\_\_

RENDERING


- 1 EXISTING BRICK PATTERN, REMOVE PAINT
- (2) NEW ALUMINUM CURTAIN WALL
- (3) NEW ALUMINUM STOREFRONT
- (4) NEW CONCRETE PANEL OR METAL PANEL
- NEW WHITE PAINTED METAL PANEL WITH CONCEALED FASTENERS
- (6) NEW PERFORATED METAL SCREEN
- 7 NEW METAL LINEAR CEILING
- (8) NEW PAINTED TUBE STEEL TRELLIS
- 9 NEW ROOF
- (10) NEW TRAFFIC COATING
- (11) NEW SIDEWALK
- (12) NEW ON-SITE PEDESTRIAN WALKWAY
- 13) NEW STAIR
- (14) NEW STREET TREES
- (15) REMOVE EXISTING SIGN
- (16) NEW LANDSCAPING
- (17) NEW ELEVATOR



**Existing Conditions** 



**Pedestrian Entry at NE Grand Ave** 



**Existing Conditions** 



Pedestrian Entry into Lobby at NE Hassalo St

## **KEY**

- 1 EXISTING BRICK PATTERN, REMOVE PAINT
- 2 NEW ALUMINUM CURTAIN WALL
- 3 NEW ALUMINUM STOREFRONT
- 4 NEW CONCRETE PANEL OR METAL PANEL
- 5 NEW WHITE PAINTED METAL PANEL WITH CONCEALED FASTENERS
- 6 NEW PERFORATED METAL SCREEN
- 7 NEW METAL LINEAR CEILING
- 8 NEW PAINTED TUBE STEEL TRELLIS
- 9 NEW ROOF
- (10) NEW TRAFFIC COATING
- (11) NEW SIDEWALK
- (12) NEW ON-SITE PEDESTRIAN WALKWAY
- 13) NEW STAIR
- (14) NEW STREET TREES
- (15) REMOVE EXISTING SIGN
- (16) NEW LANDSCAPING
- 17) NEW ELEVATOR

DESIGN **ADVICE** REQUEST 01.24.2014

EA 13--232583 DA

RENDERING

RENDERING

- 1 EXISTING BRICK PATTERN, REMOVE PAINT
- (2) NEW ALUMINUM CURTAIN WALL
- (3) NEW ALUMINUM STOREFRONT
- (4) NEW CONCRETE PANEL OR METAL PANEL
- 5 NEW WHITE PAINTED METAL PANEL WITH CONCEALED FASTENERS
- (6) NEW PERFORATED METAL SCREEN
- 7 NEW METAL LINEAR CEILING
- (8) NEW PAINTED TUBE STEEL TRELLIS
- 9 NEW ROOF
- (10) NEW TRAFFIC COATING
- (11) NEW SIDEWALK
- (12) NEW ON-SITE PEDESTRIAN WALKWAY
- 13 NEW STAIR
- (14) NEW STREET TREES
- (15) REMOVE EXISTING SIGN
- (16) NEW LANDSCAPING
- (17) NEW ELEVATOR



Perspective at Corner of NE Grand Ave and NE Hassalo St

**KEY** 

1 EXISTING BRICK PATTERN, REMOVE PAINT

4 NEW CONCRETE PANEL OR METAL PANEL

5 NEW WHITE PAINTED METAL PANEL WITH CONCEALED FASTENERS

6 NEW PERFORATED METAL SCREEN

8 NEW PAINTED TUBE STEEL TRELLIS

(12) NEW ON-SITE PEDESTRIAN WALKWAY

7 NEW METAL LINEAR CEILING

(10) NEW TRAFFIC COATING

9 NEW ROOF

13) NEW STAIR

(11) NEW SIDEWALK

(14) NEW STREET TREES

(16) NEW LANDSCAPING

17) NEW ELEVATOR

(15) REMOVE EXISTING SIGN

2 NEW ALUMINUM CURTAIN WALL 3 NEW ALUMINUM STOREFRONT

# DESIGN **ADVICE**

01.24.2014

**RED LION HOTEL REMODEL** 

# REQUEST



Perspective of Lobby Entry at Parking Deck

C.36 Materials
C.37 Screen Precedents
C.38 Trellis Precedents
C.39 Landscape Concepts
C.40 Landscape Concepts

# APPENDIX

MATERIALS

### **Berridge Thin-Line**

Versatile, maintenance-free, prefinished metal fascia, facade, wall or soffit panels for open spans.



- 24 gauge steelConcealed fastenersChannel drain interlock
- · Narrow panel with smooth appearance
- Optional wood grain or stucco
- embossed texture
- Use vertically for fascia or wall
  Open framing or solid sheathing
  Florida Product Approval









See www.berridge.com for Details and Specifications
















METAL PANEL OR CONCRETE PANEL





METAL LINEAR CEILING

WITH CONCEALED FASTENERS

Shee









EA 13--232583 DA

....

TRELLIS PRECEDENTS












TRELLIS PRECEDENTS



EA 13--232583 DA

LANDSCAPE CONCEPTS



01.24.2014

EA 13--232583 DA

LANDSCAPE CONCEPTS



Planting Concept

Red Lion

Northwest Corner