PARKS REPLACEMENT BOND

CITY COUNCIL - June 21, 2017












7 Theme Areas



NO INCREASE IN TAX RATES

POOLS

2014 PARKS REPLACEMENT BOND

NO INCREASE IN TAX RATES

BRIDGES & TRAILS

2014 PARKS REPLACEMENT BOND

households are se

ne that are nearing cut risk of closure

NCREASE IN TAX RATES

2014 Parks

2014 PARKS REPLACEMENT BOND

2014 PARKS REPLACEMENT BOND

2014 PARKS REPLACEMENT BOND

PROTECT WORKERS

RESTROOMS & URGENT REPAIRS

Replacement Bond

2014 PARKS REPLACEMENT BOND 2014 PARKS REPLACEMENT BOND NO INCREASE IN TAX RATES

and to remain rate and accounts Portland Parks & Recuestion (FPSR) but

As Portand's bear paint band perced in 1994 to paid off in 2015, we have Represents the speed to the speed in 1995 and on the 1995 and the speed to the spee will open a the object the repeat of the 1994 bond, we can now a result.

S.F. 652 million in funding to advice the crock crock a needs of our parts system.

of the most critical repairs to our ballies system.

for repairs and replacements

\$68 million

tanders support a Replacement Bond that would pay for the explacement unces and community comes structures to make them accessible to people with

NO INCREASE IN TAX RATES

NO INCREASE IN TAX RATES

Phase I Projects



Phase 2 Project List

APPROACH:

- ✓ Criteria
- **✓** Commitments
- ✓ Obligations
- ✓ Analysis
- ✓ Equity
- ✓ Short List
- ✓ Public Review Process

Phase 2 Proposed Projects



PARKS REPLACEMENT BOND

PROPOSED PHASE 2 PROJECT LIST (revised)



11 State and 15 St

The Parks Replacement Bond was passed in November 2014 authorizing \$68 million in general obligation bonds for repair and replacement projects. The first Bond project list spent \$47.6 million of the Bond; the remaining \$20.4 million will be spent in Phase 2.

PROJECT CRITERIA FOR 2014 PARKS REPLACEMENT BOND

The projects for the first Bond project list and the potential projects for Phase 2 were identified as urgent needs and prioritized with the following

- 1. Investing in projects that are immediate safety concerns or urgent repairs (urgency = highest probability of failure x highest impact of failure)
- Investing in projects that reduce bigger costs later on
- 3. Responsible repairs for general deferred maintenance needs
- 4. Investing in energy efficiency
- 5. Increasing accessibility for all
- 6. Restoring services that are currently closed

The following list describes what remains to fulfill the obligations of the original Bond language for each theme area and lists potential projects for Phase 2 of the Parks Replacement Bond. Phase 1 projects are currently underway.

	SITE	PROPOSED PROJECT	DESCRIPTION					
[PLAYG	ROUNDS	Replace or build 10 to 20 play structures that are closed, at risk of closure or deficient. At least \$5M for the life of the Bond.					
	Accomplished by Bond Phase 1:		\$9M spent, 7 playgrounds					
	Required for Bond Pha	ase 2:	3 playgrounds					
	Gabriel Park	Playground renovation	No accessibility. Playground design improvement needed. Adjacent to SW Community Center (SWNI)					
*	Gilbert Primary Park	Playground renovation	Some of the oldest equipment in the system (1966). Play equipment condition poor. Neighborhood park (EPNO)					
*	Glenhaven Park	Playground renovation	Some of the oldest equipment in the system (1977). Neighborhood park. More play pieces to be removed due to lead (CNN)					
	Other Playground renovations considered include: Argay (EPNO), DeWitt (SWNI), Hancock (CNN), Overlook (NPNS), Pier (NPNS),							
		PLAY PIECES	Replace play equipment that has needs repair and/or has tested positive for lead-based paint. Up to \$3M designated for Phase 2. A minimum of 30 parks will be completed.					
*	Repair or Replace Equipment: Albert Kelly, Argay, Berkeley, Bloomington, Colonel Summers, Flavel, Fulton, Hancock, Irving, Knott, Laurelhurst, Mt Tabor, Pendleton, Piccolo, Sewallcrest, University Park, Washington, Wilkes, Wilshire, Woodstock							
		Address Drainage and Replace Engineered Wood Fiber (ADA-Approved Wood Chips): Burlingame, Clinton, Harney, Patton Square, Peninsula, Pier, Portsmouth, South Park Blocks, Sunnyside School, Woodlawn						
j	TRAILS 8	BRIDGES	Preserve access to natural areas and open spaces by repairing bridges and trails (at least \$5M during the life of the Bond).					
	Accomplished by Bond	d Phase 1:	\$3.9M spent					
	Required for Bond Phase 2:		\$1.26M					
	Foley-Balmer Natural Area	Replace Trail Bridge	Replacement bridge					
	Marshall Park	Replace Trail Bridge	Replacement bridge					
	Springwater Trail Bridge #140 (by Circle Ave / Powell Butte)	Replace Trail Bridge Decking	Replacement of bridge decking					
	Other Bridge Replacement candidates considered include: Springwater Bridge #141 (by Telford Rd, SE 242nd) and Springwater Bridge #53 (by Telford Road, SE 242nd). Both are in Gresham							
*	Indicates a Health/Saf	ety/Environment (HSE)						

Phase 2 Public Involvement

PUBLIC OUTREACH APPROACH

- **√** 6 Neighborhood Coalitions/Land Use Committees
- ✓ 2 Town Halls
- **✓ Parks Board**
- **✓** Budget Advisory Committee
- **✓ Bond Oversight Committee**
- **✓ Portlanders Stand with Immigrants & Refugees**
- ✓ Next Door, Twitter, Facebook, Web, Emails
- **√** Signs, Comment Forms


Phase 2 Proposed Projects

PARKS REPLACEMENT BOND

PROPOSED PHASE II







Gilbert Primary Park

Playground Renovations

3 Playgrounds







Glenhaven Park



Play Piece Replacements

• 30 Playground Locations



Albert Kelly Park



Trails and Bridges

• 3 Bridges



Marshall Park Bridge




Foley Balmer Bridge



Springwater Trail Bridge

Pools

• 1 Peninsula Pool





Accessibility

• 3 Projects



Multnomah Arts Center

Mt. Tabor

WO Number	Property	Asset	Description		Service	Location
239431	Floyd Light Park	Drinking Fountains	Fountain protrudes 11-1/2" from wall at 32-3/4" AFF (protrusion more than 4" must be mounted below 27" or above 80" req). Install wing wall, State Codes:—, 307.2 Federal Codes:307		ADA Barrier Remediation	10 - 7 Drinking Fountain
239432	Floyd Light Park	Drinking Fountains	The bubbler height is 48-3/4" AFF (38" min to 43" max for a standing person fountain). State Codes:—Federal Codes:602,7		ADA Barrier Remediation	10 - 7 Drinking Fountain
228752	Floyd Light Park	Access Systems	Visible fire alarm is 79" AFF (80" min to 96" max, or 6" below the ceiling, whichever is lower). State Codes:— Federal Codes:702.1		ADA Barrier Remediation	17 - 3 Corridor / Aisle
228738	Floyd Light Park	Access Systems	A tactile and Braille EXIT sign is not provided. State Codes: Federal Codes:216.4, 703.4		ADA Barrier Remediation	8 - 46 Door/Gate
228739	Floyd Light Park	Access Systems	A tactile and Braille permanent room sign is not provided. State Codes: Federal Codes:216.2		ADA Barrier Remediation	8 - 47 Door/Gate
228740	Floyd Light Park	Access Systems	Pull side slope is 2.2% to 2.5% (2.0% max), State Codes;— Federal Codes:404.2		ADA Barrier Remediation	8 - 47 Door/Gate
228741	Floyd Light Park	Access Systems	Double door: closer sweep time is 4 seconds on southern leaf (5 seconds min). Door opening force is 10 lbs on both leaves (8-1/2 lbs max for exterior door). State Codes:—, 1101.2.2.5 Federal Codes:404.2		ADA Barrier Remediation	8 - 48 Door/Gate
228742	Floyd Light Park	Access Systems	Threshold has a height of 1" (1/4" max, up to a ½" with a bevel). State Codes:— Federal Codes:404.2		ADA Barrier Remediation	8 - 48 Door/Gate
228743	Floyd Light Park	Access Systems	A tactile and Braille permanent room sign is not provided. State Codes: - Federal Codes:216.2		ADA Barrier Remediation	8 - 48 Door/Gate
238272	Floyd Light Park	Signs	The baseline of the top line of tactile characters on the permanent room sign is 63-7/8" AFF (48" AFF min to 60" AFF max). State Codes:— Federal Codes:703.4		ADA Barrier Remediation	9 - 19 Sign
WO Number		Asset	Description	Date Due	Location	Requester
254494	Floyd Light Park	Doors - Exterior EPCC	Add door stops to front doors	11/8/2016		
259451	Floyd Light Park	Doors - Exterior EPCC	The handicap button for the front doors needs a new battery	3/31/2017	Front doors	Elizabeth Corrigan
203813	Floyd Light Park	Lighting - EPCC	Lights out (burned out? turned off?) in front entrace foyer, and the outdoor front entry (some are on, so I think the two that are not on must be burned out)	11/3/2014	front foyer & front entrance	Abbe MacFarlane
218135	Floyd Light Park	East Portland Community Center and Pool	ADA door opener, located in lobby near front door (not in foyer) - not working; may need battery	9/11/2015	Near front entry	Abbe MacFarlane



East Portland Community Center

Pier Park

Restroom & Other

- 3 Roofs
- 4 Other Urgent Repairs



Matt Dishman

Montavilla








Looking Forward

PARKS REPLACEMENT BOND

PHASE I + EXPANSION PROJECTS
- AND PROPOSED PHASE II







THANKYOU!

Item 703

Accept the Bond Phase 2 Project List for the \$68,000,000
Parks 2014 General Obligation Bond (Report)

CONTACT INFO:

Lauren McGuire
Parks Development Program Manager
City of Portland
503.823.5591
Lauren.McGuire@PortlandOregon.gov

Item 704

Item 704

Authorize \$39,576,793 of general obligation bonds for parks projects and refunding bonds. (Ordinance)