Site	РВОТ	ODOT	Notes
802 and 814 NE Jarrett St	No	No	No issues in the vicinity
			Killingsworth between 72 and I-205 is an area of concern for both ODOT and
5606 NE Killingsworth and 5555 NE Sumner	No	No	PBOT. v/c meets current standards.
			There are some failing instersections in the vicinity of the Freemont Bridge
4304 N Vancouver	No	No	access about 7 blocks to the south. No issues in the immediate vicinity.
8245 NE Fremont St	No	No	No issues in the vicinity
			Killingsworth between 72 and I-205 is an area of concern for both ODOT and
7250 NE Killingsworth St	Yes	Yes	PBOT. v/c meets current standards, however.
			There are some failing instersections in the vicinity of the Freemont Bridge
4511 N Williams Ave	No	No	access about 7 blocks to the south. No issues in the immediate vicinity.
			Inner Powell (about 8-10 bocks to the South) exceeds v/c standards. Train-
2408 SE 16th Ave	No	No	related conjestion at SE 11/12/Division.
4525 SE Stark St	No	No	No issues in the vicinity
4710-4730 SE Stark St	No	No	No issues in the vicinity
743 SE 76th	No	No	No issues in the vicinity
			Close to an ODOT offramp in the West Portland Town Center. There is a link
			here that is exceeding v/c standards - but it is within the study area of the
			Town cenetr Plan, which map rpopose additional TSP projects. There will be
4729 SW Taylors Ferry Rd	No	No	a new LRT station nearby with SW Corridor.
2374 SW Vermont	-	No	
	No	NO	No issues in the vicinity

This info was a review of modelling results from the Comp Plan (Volume 1.4 of the DLCD Record for Task 4 of Periodic Review, Ord. 187832)