

Bureau of Planning and Sustainability Innovation. Collaboration. Practical Solutions.

Date:	January 22, 2020
То:	Stephanie Beckman, Bureau of Development Services
From:	Mindy Brooks, Bureau of Planning and Sustainability
Cc:	Sallie Edmunds, Planning Manager, Bureau of Planning and Sustainability Jeff Caudill, Bureau of Planning and Sustainability Ethan Brown, Bureau of Planning and Sustainability
RE:	Zoning Map Error Correction Request for 3699 N Hayden Island Drive, R323354, QS 1627, QS 1628 and QS 1728; IQ 19-245039

Robert Smith, representing Canoe Bay, LLC, submitted a request for a zoning map error correction for the property located at 3699 N Hayden Island Drive. In the request, Robert Smith suggests that the environmental overlay zone on the property is mapped in error because the overlay zone boundary was intended to protect wetlands and there are no wetlands present on the site (Attachment A: Submittal).

According to the applicable zoning code, 33.855.070, Corrections to the Official Zoning Maps, corrections can be made for mapping errors including:

A.1. A map line that was intended to follow a topographical feature does not do so. Topographical features include the tops and bottoms of hillsides, the banks of water bodies, and center lines of creeks or drainage ditches; or

A.2 There is a discrepancy between maps and on balance there is sufficient evidence of legislative intent for where the line should be located. (33.855.070.A.2)

Based on review of the *Columbia Corridor Industrial/Environmental Mapping Project* (1989) inventory and ESEE analysis, the *Natural Resources Inventory* (2012), the zoning history for Quarter Sections 1627, 1628 and 1728, and the information submitted by the applicant, I have concluded that an environmental overlay zone mapping error exists on the property in question. It appears that the current location of the Environmental Conservation overlay zone is incorrectly placed.

Although based on <u>existing</u> regulations an error exists on the site, which results in removal of a significant portion of the conservation (c) overlay zone, the entire site is within the 100-year floodplain and 1996 flood inundation area (Attachment B). Title 24 rules apply to the flood



areas. In addition, the Bureau of Planning and Sustainability is undertaking a project to update regulations to maintain property owner access to the National Flood Insurance Program and to ensure protection of endangered and threatened salmon and steelhead. These updates are expected to extend new regulations to the site. (More information about that at the end of this letter.)

Analysis

The property is located in Resource Site 71 Columbia River and Bankline of the *Columbia Corridor Industrial/Environmental Mapping Project* (1989). The inventory is documented as Resource Site 71 and the ESEE was conducted and a decision was made for the Hayden/Tomahawk Island Subdistrict and for the Columbia River and Bankline (Attachment C and D).

In the inventory, the natural resource features and functions identified in Resource Site 71 include (see Attachment C):

- River
- Riverine shore
- Wetlands
- Forest vegetation
- Shrubland vegetation
- Floodplain

Using the information presented in the inventory, the Economic, Social, Environmental, and Energy Analysis and recommendations was completed (see Attachment D). The ESEE reviews and evaluates existing and potential conflicting uses to best determine the level of protection for natural resources within the identified resource sites. Resource Site 71 was not explicitly addressed in the ESEE; instead, Resource Site 71 was lumped into a recommendation for the Columbia River and Bankline.

The ESEE states on page 163 that an ec (environmental conservation) overlay zone is recommended for the Columbia River and bankline. The values to be protected are "Riparian strip for wildlife habitat, visual amenity, erosion control. Drainageway functions, including fish habitat, drainage, flood storage, desynchronization, erosion control, sediment trapping, and pollution and nutrient retention and removal for the same area. The "same area" is interpreted to mean "riparian strip" which is the same geography as the "bankline" and is shown on the inventory map on page 110 (Attachment C). There is no measurement provided for the width of the riparian area (aka, bankline) within the inventory or ESEE.

The city-wide *Natural Resources Inventory* (2012) includes an update to the natural resource features based on current data and GIS research. The NRI includes the waterbodies, the ordinary high water mark, the flood area, wetlands and vegetation (Attachment B). The area below the ordinary high water mark is considered part of the Columbia River because that area is seasonally inundated with water during normal high flows. The area landward of the ordinary high water mark is considered the river bank and riparian area. According to best available science adopted in the 2012 NRI, the minimum width of riparian areas around rivers, streams and wetlands is 50 feet, but could be considerably wider depending on functions.



The zoning history for Quarter Section 1627, 1628 and 1728 shows that the environmental conservation overlay zone boundary is not applied in accordance with the Columbia Corridor Industrial/Environmental Mapping Project inventory or ESEE recommendations (Attachment E). Based on the inventory map on page 110 of the inventory and the ESEE recommendation, the conservation overlay zone should have been applied only to the Columbia River and riverbank.

Conclusion and Recommendations

According to 33.855.070, Corrections to the Official Zoning Maps, corrections can be made for mapping errors including:

- A.1 A map line that was intended to follow a topographic feature does not do so. Topographic features include the tops and bottoms of hillsides, the banks of water bodies, and center lines of creeks or drainage ditches.
- A.2 There is a discrepancy between maps and on balance there is sufficient evidence of legislative intent for where the line should be located. (33.855.070.A.2)

There is evidence that an environmental overlay zone mapping error exists on the property in question. The error meets criterion A.2.

<u>Criterion A.2</u> – Based on the inventory map on page 110 of the inventory and the ESEE recommendation, the conservation overlay zone should have been applied only to the Columbia River and riparian area. The current extent of the conservation overlay zone extends beyond the riparian area. Therefore, the environmental overlay zone should be corrected to include only Columbia River and riparian area.

Staff recommends that Bureau of Development Services process a Type II map error correction to amend the official zoning map. Attachment F shows the existing and recommended location of the conservation overlay zone on the property. The riparian area is identified in the 2012 NRI as the area landward of the ordinary high water mark that is providing riparian corridor functions and the minimum width of any riparian area is 50 feet. An additional 25 feet of transition area should be applied landward of the resource area.

Staff also wanted to highlight an issue that was identified in reviewing the relevant documents for this site. Based on the wetland delineation conducted by Pacific Habitat Services, there are no wetlands on the site. The city-wide Natural Resources Inventory will be updated to remove the wetlands.

The Bureau of Planning and Sustainability (BPS) will be starting a comprehensive update to regulations related to the floodplains to maintain property owners access to the National Flood Insurance Program and to ensure protection of endangered and threatened salmon and steelhead. At that time, the site will be considered for regulations that may limit uses or require additional mitigation. For more information about the floodplain project, please contact Ethan Brown at 503-823-7920.



Attachments:

- Attachment A: Submittal
- Attachment B: Natural Resources Inventory.
- Attachment C: Columbia Corridor Industrial/Environmental Mapping Natural Resources Inventory
- Attachment D: Columbia Corridor Industrial/Environmental Mapping ESEE
- Attachment E: Zoning History
- Attachment F: Existing and Recommended Environmental Conservation Overlay Zone



IQ 19-245039



CITY OF PORTLAND, OREGON - BUREAU OF DEVELOPMENT SERVICES

1900 SW Fourth Avenue • Portland, Oregon 97201 • 503-823-7526 • www.bds.ci.portland.or.us

Zoning Map Error Correction Request Form 33.855.070 Corrections to the Official Zoning Maps

The Director of the Bureau of Development Services may initiate and approve a review following the Type II procedure for the types of discretionary corrections to the Official Zoning Maps listed below. Nondiscretionary corrections to the Official Zoning Maps may be initiated by the Director of Planning as described in Section 1.01.037 of the Portland City Code.

- A. Mapping errors. The correction may be made for mapping errors such as:
 - A map line that was intended to follow a topographical feature does not do so. Topographical features include the tops and bottoms of hillsides, the banks of water bodies, and center lines of creeks or drainage ditches; or
 - 2. There is a discrepancy between maps and there is clear legislative intent for where the line should be located.
- B. Movement of the reference item for the map line. The correction may be made when it can be clearly shown that a map line is based on the location of a reference item that has since been moved. Reference items are rights-of-way, tentative rights-of-way, utility easements and similar type items. Map line changes in these cases must not be more than a trivial change to the map pattern and must not result in any significant impacts to abutting lots.
- C. Land within the Urban Growth Boundary. The correction may be made when it involves the removal of the Future Urban overlay zone from properties that are now within the Urban Growth Boundary.

1.01.037 Planning Director Authority to Correct Portland Zoning Code Maps.

Subject to the approval of the City Attorney, the Director of the Bureau of Planning shall have the authority to correct Portland Zoning Code maps, including the City's Official Zoning Map:

- 1. When a map line does not match the legal description or map referenced in the ordinance or approved land use decision that applied the designation; or
- 2. When there is a discrepancy between maps and there is clear legislative intent for where the line should be located; or
- 3. When the Open Space zone has been applied to property in private ownership that is not in an open space use, or is not receiving special tax considerations because of its status as open space.

Zoning map corrections initiated under this section must be clear and objective. Discretionary map corrections must be processed under the procedures set forth in PZC 33.855.070.

Please provide the following information using the form on the other side, and submit to Planning and Zoning, Bureau of Development Services, 1900 SW Fourth Avenue, Rm 1500, Portland, Oregon

Your request will be processed within 6 weeks of the date of this request. The BDS Director has the discretion to notify an applicant that additional time is needed to review this request.

- Applicant name
- Address or tax account number of property in question
- The City's environmental resource inventory plan name and resource site number, if applicable
- City Land Use Review case numbers, if applicable, for the property in question (include all case numbers and brief description of case(s) pertaining to potential map error)
- Reason for requesting a map error correction review
- Site plan showing all development and the current location of all base zone and overlay zone lines

Zoning Ma	p Error	Correction	Request	Form
-----------	---------	------------	---------	------

Date	019			
Applicant Inform	nation			
Applicant Name	Canoe I	Bay, LLC, Rober	t E. Smith	
Applicant Telephone	503 381-3560	FAX	e-mail address	Rsmith291@hotmail.com
Applicant Address	7327 S.W. Barnes	Rd. PMB 120, Po	rtland, OR 97225-6119	
Site Information		clude addresses a	ind tax account numbers for	r all lots
3699 N. Hayden I R323354, Section	sland Dr., Portland, O 28 2N 1E, TL 100 2.5	IR 97217, Map N 57 Acres	umber 2N1E280030, Prop	erty ID Number
Owner of Sito	Canoe Bay, LLC SD	P. LLC		

City's Environmental Resource Inventory Plan and Resource Site Number*, if applicable ____

Land Use History

Please provide all Land Use Review case number(s) affecting the site, and brief description of any cases pertaining to the request*

Case File EA 15-127100

In late 2017 and early 2018, while marketing our land for sale, we were informed by multiple buyers they would not be able to complete their purchases. The reasons cited in both cases were the presence of wetland areas noted in the public records. As such, in March of 2018, we commissioned a wetland delineation report (attached) through Pacific Habit Services which in fact confirmed that NO wetland areas exist on the property. We subsequently also learned the City's original process for mapping wetland areas over our property had been "completed in an arbitrary fashion," and without any science (or even a physical visit to the site).

Finally, it is worth noting that despite our proper distribution of the "clean" wetland delineation report to all involved State of Oregon Governmental Agencies, the Corps of Engineers, Division of State lands, and to the City of Portland, our property is (i) still mistakenly labeled as having wetland areas present, and (ii) subject to the limitations of being in an environmental overlay zone (the application of which would not have been placed on our property had the land not been designated with wetlands in the first place).

Since the erroneous wetland conclusions were already of record when the City's subsequent application of Environmental and Conservation (c) overlay zones were put in place (including on our property), we now wish to have the record corrected and this overlay zone removed.

Describe Error

Must meet one or more of the criteria listed in 33.855.070 on the front of this form


Our request meets the requirement of 33.855.070, the overlay zone was intended to follow a topographic feature and it does not.

Please attach site plans.


*information available in the Development Services Center, 1900 SW Fourth Avenue, First Floor

2

zone_map_error 8/28/03




Attachment C: Columbia Corridor Industrial/Environmental Mapping Project, Natural Resources Inventory









SITE 71, continued

NEIGHBORHOOD: Kenton, East Columbia (West, Central Columbia Corridor)

ZONING*: M1,M2(l,n), C2,C2(l,n), R10(l,n) COMPREHENSIVE PLAN: Industrial, Commercial, Residentia DATE OF INVENTORY: September 1988

OWNERSHIP: Private, Port of Portland, State of Oregon

* The lower case symbols represent overlay zones. All upper case symbols represent base zones. See Appendix B Tr a description of each zone.

CLASSIFICATION**: cerine, Lower Perennial/Tidal,

Unconsolidated Shore, Sand, Permanently Flooded.

Riverine, Lower Perennial/Tidal, Unconsolidated Shore, Sand, Seasonally Flooded.

Palustrine, Emergent Wetland, Persistent, Seasonally Flooded.

Palustrine, Scrub-Shrub, Broad-leaf Deciduous, Seasonally and Intermittently Flooded.

Palustrine, Forested, Broad-leaf Deciduous, Seasonally and Intermittently Flooded.


** In addition, uplands may be present.

OBSERVATIONS AND COMMENTS: This is a highly disturbed, largely developed portion of the Columbia River. Levees maintained by the drainage districts, which extend along the length of the site, must be kept clear of large trees and protected from erosion. This results in vegetation that is primarily grasses and shrubs, with occasional small groves of trees.

Open recreational activities, including launching ramps, beaches, and bicycle paths are the predominant activity along the eastern portion. Commercial and industrial activities including moorages, and residential development are in the central and western sections of the site.

WILDLIFE HABITAT INVENTORY SCORE: 18





COLUMBIA CORRIDOR: RIVERGATE - TERMINAL 4 & HAYDEN/TOMAHAWK ISLAND

CITY OF PORTLAND

12

. .

INVENTORIED WATER FEATURES

118


	Levelof		
Site	Protection	Values to be Protected	
55,	en ec	High quality uplands and wetlands for all of Smith and Bybee Lakes, the Ramsey Lake mitigation area, and the blind slough south of the Columbia Slough containing wapato wetlands for all values identified in the summary WF41 table.* Drainageway functions, including fish habitat, drainage, flood storage, desynchronization, erosion control, sediment trapping, and pollution and nutrient retention and removal for the same area. The remainder of the inventory site for all values identified in the summary table.* Drainageway functions, including fish habitat, drainage, flood storage, desynchronization, erosion control, sediment trapping, and pollution and nutrient retention and removal for the same area.	
54	none at this	s time	
Columbia River and Bankline			

ec


4


Riparian strip for wildlife habitat, visual amenity, erosion control. Drainageway functions, including fish habitat, drainage, flood storage, desynchronization, erosion control, sediment trapping, and pollution and nutrient retention and removal for the same area.

The Summary Table is located in the front of the Inventory Section of this report.



(11:





1	ZONING REVISED:	CITY OF PORTLAND, BUREAU		
Current Zoning	05-13-2011	OF PLANNING & SUSTAINABILITY		
 Maximum Potential Zaning on part 	BASEMAP ACQUIRED: 07 - 2010	0' 100' 200' 300' SCALE IN FEET		
 Zoning as per Comprehensive Plan 	LEGAL DESCRIPTION: SE 1/4 SEC.	1628		
State ID Map Boundary	28 - 2N - 1E	1020		

rrent Zoning	zoning revised: 05-13-2011	CITY OF PORTLAND, BUREAU OF PLANNING & SUSTAINABILITY		
ximum Potential	BASEMAP ACQUIRED: 07 - 2010	0' 100' 200' 300' SCALE IN FEET		
ning as per mprehensive Plan te ID Map Boundary	LEGAL DESCRIPTION: SE 1/4 SEC. 28 - 2N - 1E	1628		

(1629)

CITY BOUNDARY

