
Development Services

From Concept to Construction



More Contact Info (http://www.portlandoregon.gov//bds/article/519984)





APPEAL SUMMARY

Ctatura	Hold for	Additional	Information
Status:	Hold for	Additional	intormation

Appeal ID: 20745	Project Address: 3547-3561 SE Milwaukie Ave		
Hearing Date: 8/14/19	Appellant Name: Chris Chilberg		
Case No.: B-027	Appellant Phone: 503-638-4245		
Appeal Type: Building	Plans Examiner/Inspector: Stephanie Hansen, Peter Drake, Steve Mortensen		
Project Type: commercial	Stories: 2 Occupancy: R-2 Construction Type: V-B		
Building/Business Name:	Fire Sprinklers: No		
Appeal Involves: Alteration of an existing structure	LUR or Permit Application No.: 19-171148-CO		
Plan Submitted Option: pdf [File 1]	Proposed use: Multi-family (8 unit apt. complex)		

APPEAL INFORMATION SHEET

Appeal item 1

Code Section	OSSC 1009.7.2

Requires	Riser height 7 in	ch maximum and	d rectangular tread	depth 11 inch minimum.
----------	-------------------	----------------	---------------------	------------------------

Proposed Design

We propose the stairs to the upper landing will have a tread length of 11 inches, with a minimum of 10 inches horizontal dimension from nose to nose of tread. The risers shall not exceed 7-1/2 inches (the actual dimension will be slightly over 7" - 7.01 inches per riser). Each stairway shall have 17 risers (119-1/4" total height from the lower walkway to the balcony).

Reason for alternative If the stair tread length is increased to 11" horizontal from nose to nose as required by the current code, the bottom of the stairs will extend beyond their current termination point, intruding into the egress pathways for the lower floor occupants. This would result in a major revision to the existing egress pathways for the lower floor. The existing stair construction was in a state of decay, and replacement was required. The original stairs for this building were as described above (we have provided a copy of the original stair design for reference). The intent is to match exactly the existing stair tread length and riser height.

> Replacing the stairs in a manner that matches the existing conditions maintains the current level of safety.

Appeal item 2

OSSC 1012.6 and OSSC 1012.1 **Code Section**

Requires Handrails and handrail extensions.

Proposed Design

We propose the original guardrail be re-used, without adding a new handrail (no handrail existed on the existing stairs). The existing guardrail and its attachments will be upgraded as required for structural purposes (to withstand code level loading requirements), as well as safety requirements (additional elements added to prevent the passage of a 4" diameter sphere).

Reason for alternative The addition of a hand rail will require a major revision to the existing egress pathways. Per current code requirements, the top of a handrail must be horizontal, and extend 12" beyond the top riser. Furthermore, a handrail must extend beyond the bottom riser by at least a tread length. This would result in revisions to the framing of the upper floor landings, mid height landing (at south stair), and the existing egress pathways for the lower floor. As noted previously, the intent is maintain or increase the level of safety, while repairing the degraded elements of the balcony. The proposed design significantly increases the level of safety (guardrail and attachments to meet current code standards).

APPEAL DECISION

- 1a. Existing stair tread length to remain: Hold for additional information.
- 1b Existing stair riser height to remain: Hold for additional information.
- 2. Omission of handrail extensions: Hold for additional information.

Appellant may contact John Butler (503 823-7339) with questions.

