

Mr. Stenen Hendricks
2908 1st National Bank Tower
Portland, Oregon 97204

Columbia
Street
1980

August 19, 1980

TO WHOM IT MAY CONCERN:

Regarding the synchronization of the traffic control signals at S.W. 13th Avenue at S.W. Columbia Street and S.W. 13th Avenue at S.W. Clay Street, on December 21, 1978, at 1:10 P.M., our records show the following:

For vehicles eastbound on Columbia at 13th at Columbia:

Green----22.0 Seconds
Yellow--- 3.0 Seconds
Red-----27.0 Seconds

For vehicles southbound on 13th at 13th at Clay:

Green----22.0 Seconds
Yellow--- 3.0 Seconds
Red-----27.0 Seconds

The southbound Green at 13th at Clay begins 13.0 seconds before the eastbound Green at 13th at Columbia. The southbound Red at 13th at Clay begins 12.0 seconds after the beginning of the eastbound Green at 13th at Columbia.

There was no report of trouble at S.W. 13th at Columbia or S.W. 13th at Clay on December 21, 1978.

I, Jack F. Mason, District Signal Engineer, certify and affirm that I am a keeper of the public records regarding the foregoing

information and that the foregoing information is a true and correct copy of such records.

Jack F. Mason

Subscribed and sworn to before me this 19th day of August, 1980.

Notary Public for Oregon
My commission expires May 15, 1984

APPROVED:

Richard Speer,
Assistant City Traffic Engineer