

1455 SW BROADWAY

BDC / SW BROADWAY LLC GBD ARCHITECTS INC.


APPENDIX C - DESIGN STUDIES

APPENDIX C: DESIGN STUDIES


- 1. NE CORNER GLAZING
- 2. PARKING GARAGE ENTRANCE
- 3. DISTRIBUTION OF SPANDREL GLAZING
- 4. BIRD ROOSTING CONCERNS
- 5. ENTRY / LANDSCAPE ALONG SW BROADWAY

NE CORNER GLAZING


Study changing the NE corner to more glazing, removing the terracotta at the corner.




- THE TERRACOTTA FRAMES THE SHARED BUILDING LOBBY ENTRANCES ALONG BROADWAY
- THE TERRACOTTA FRAMES THE RESTAURANT AND LOUNGE SPACES AND CAPTURES THE CANOPIES



- RETAIL CORNER IS HIGHLIGHTED BY CREATING A CRYSTALLINE BOX THAT REACHES OUTWARD
- THIS SEPARATES USES AND CREATES HIERARCHY










TERRACOTTA REDUCED TO 10'-0" IN WIDTH FACING BROADWAY


PARKING GARAGE ENTRANCE

Move parking garage security gate closer to the property line.






A. REPRESENTATIVE IMAGE OF GARAGE DOOR





A. GARAGE ENTRY SIDE ELEVATIONS






PARKING GARAGE ENTRANCE [PREVIOUS]





<u>INDIGO / 12W</u>

- ROLL-UP SECURITY GRILL AT PROPERTY LINE
- EXTERNAL PARKING ACCESS CONTROLS







PARK AVENUE WEST

- OPEN GARAGE ENTRY
- NO SECURITY GATE
- EXPOSED, UNPAINTED CMU WALLS
- PARKING TICKET GATES AT BOTTOM OF RAMP


GBD Architects Incorporated

LU 15-281248 DZM - DESIGN REVIEW BDC/SW Broadway, LLC | 1455 SW Broadway • April 11, 2016






A. REPRESENTATIVE IMAGE OF GARAGE DOOR




A. GARAGE ENTRY SIDE ELEVATIONS



PARKING GARAGE ENTRANCE [PROPOSED]


BALANCE OF SPANDREL GLAZING

Study the distribution of spandrel glazing on building elevations.





SPANDREL GLAZING DIAGRAM


PREVIOUS



- REDUCED SPANDREL GLAZING IN HOTEL LEVELS
- ADDED VISION GLAZING
- 1,170 SF OF VISION GLAZING ADDED (INCLUDES WEST ELEVATION NOT SHOWN)









SILL HEIGHT: 2'-0" AFF

HEAD HEIGHT: 8'-7" AFF







SILL HEIGHT: 2'-0" AFF

HEAD HEIGHT: 10'-0" AFF











BIRD ROOSTING CONCERNS

Research the potential of birds roosting on the building, particularly at curtainwall fin locations.








INDIGO / 12W BIRD ROOSTING CASE STUDY

The Indigo / 12W building opened in 2009. Constructed of a glass curtainwall system, similar to the proposed Broadway Tower, the Indigo is comprised of several areas of balconies and projecting curtainwall fins, both exposed and with overhead protection. These elements are similar to the conditions that were of concern for the potential for bird roosting.

The General Manager for the Indigo was contacted with an inquiry about any issues related to birds and the building. In the nearly 7 years that the building has been open, there have been no reported issues with birds roosting on any balconies, roofs, or projecting fins.




BIRD ROOSTING DETERRENTS

- NO OVERHEAD PROTECTION FOR BIRDS
- MOST ROOSTING LOCATIONS INVOLVE PROTECTION FROM THE ELEMENTS AND FROM PREDATORS FROM ABOVE
- VISION GLASS AT CORNER AND CANTILEVER CONDITIONS WHERE
 ACTIVITY INSIDE THE BUILDING WILL BE NOTICEABLE
- ROOSTING POTENTIAL OFTEN CANNOT BE PREDICTED AND
 REMEDIATION TACTICS CAN BE MADE IN THE FUTURE
 (source: Audubon Society)

GBD Architects Incorporated


ENTRY / LANDSCAPE ALONG SW BROADWAY

Study the entry sequence along SW Broadway. Landscape planters hinder permeability of building entrance.




GROUND FLOOR LANDSCAPE [PREVIOUS]

LU 15-281248 DZM - DESIGN REVIEW BDC/SW Broadway, LLC | 1455 SW Broadway • April 11, 2016





APPENDIX C: 24 GBD Architects Incorporated




A. BROADWAY ENTRY SEQUENCE

NOT TO SCALE





NOT TO SCALE



NOT TO SCALE

LANDSCAPE SECTIONS [PROPOSED]

NOT TO SCALE



A. BROADWAY ENTRY SEQUENCE

NOT TO SCALE







6°THICK ARCHTECTURAL PRECAST CAP,
LENGTH PER PLANS, THERMAL RINSH

SEALANT OVER BACKER ROD AT JOINT,
TYP.
MCDHANGALLY FASTENED STRAP
ANCHOR, TYP.
MORTAR BED
TYPE 16 SS DOWEL
WATERPROOFING AND FILTER FABRIC,
CONTINUOUS, STOP 2° BELOW FG.
GROWING MEDIUM, TYP, REF. SPECS
2° THICK ARCHITECTURAL
CONCRETE CLADING,
THERMAL RINSH

4° CONCRETE PAVING


FINISHED GRADE AT ADJACENT
PAVING, REF GRADING

EXPANSION JOINT

WATERPROOFING AND DRAINAGE,
REF. ARCH
#5 @ 12° O. C. EACH WAY

STRUCTURAL INSULATION,
REF. ARCH / STRUCTURAL





B. LANDSCAPE PLANTER

C. PLANTER WALL SECTION

D. SEATING INSPIRATION

E. SEATING PLINTH SECTION

NOT TO SCALE

BROADWAY ENTRY SEQUENCE [PROPOSED]