1 Emmanuel Temple Church

1033 N Sumner St R210702



- BLI Constraints (Individual)
- ✓ Transportation Capacity (conTranCap)
- ☑ Highway Interchanges (conTranInt)
- ✓ Substandard Streets (conTranSub)
- ✓ Water System (conWater)
- ✓ Sewer (conSewer)
- ✓ Stormwater (conStorm)

- Paved without curb
- Paved with curb
- Unpaved
- Impassable ــــ ا


2 Mount Scott Church of God

10603 SE Henderson St R336867, R336872, R336873, R588872



- BLI Constraints (Individual)
- ✓ Transportation Capacity (conTranCap)
- ☑ Highway Interchanges (conTranInt)
- ✓ Substandard Streets (conTranSub)
- ✓ Water System (conWater)
- ✓ Sewer (conSewer)
- ✓ Stormwater (conStorm)

- Paved without curb
- Paved with curb
- Unpaved
- Impassable



3 Habitat for Humanity/Metro

2401 SW Taylors Ferry Rd (9134 SW 25th Ave) R163068, R163067



- BLI Constraints (Individual)
- ✓ Transportation Capacity (conTranCap)
- ☑ Highway Interchanges (conTranInt)
- ✓ Substandard Streets (conTranSub)
- ✓ Water System (conWater)
- ✓ Sewer (conSewer)
- ✓ Stormwater (conStorm)

- Paved without curb
- Paved with curb
- Unpaved

4 Dianne Clay residence

4515 N Mississippi Ave R135550



- BLI Constraints (Individual)
- ▼ Transportation Capacity (conTranCap)
- ☑ Highway Interchanges (conTranInt)
- ✓ Substandard Streets (conTranSub)
- ✓ Water System (conWater)
- ✓ Sewer (conSewer)
- ✓ Stormwater (conStorm)

- Paved without curb
- Paved with curb
- Unpaved
- Impassable ــــ ا

5 Mount Tabor Presbyterian Church

5441 SE Belmont St R221875, R221878, R221879, R221880, R221881



- BLI Constraints (Individual)
- ✓ Transportation Capacity (conTranCap)
- ☑ Highway Interchanges (conTranInt)
- ✓ Substandard Streets (conTranSub)
- ✓ Water System (conWater)
- ✓ Sewer (conSewer)
- ✓ Stormwater (conStorm)

- Street Surface
- Paved without curb
- Paved with curb
- Unpaved
- ــــ Impassable


6 Robison Jewish Home

Parcel east of 6140 SW Boundary St R329032



- BLI Constraints (Individual)
- ✓ Transportation Capacity (conTranCap)
- ✓ Highway Interchanges (conTranInt)
- ✓ Substandard Streets (conTranSub)
- ✓ Water System (conWater)
- ✓ Sewer (conSewer)
- ✓ Stormwater (conStorm)

- Paved without curb
- Paved with curb
- Unpaved



7 Evergreen Community / Tillamook Preschool

935 NE 33rd Ave R316847



- BLI Constraints (Individual)
- ✓ Transportation Capacity (conTranCap)
- ☑ Highway Interchanges (conTranInt)
- ✓ Substandard Streets (conTranSub)
- ✓ Water System (conWater)
- ✓ Sewer (conSewer)
- ✓ Stormwater (conStorm)

- Paved without curb
- Paved with curb
- Unpaved
- Impassable ــــ ا