June 11,1927. Wakefield-Fries. 81-4th St. City. Re: 546 Rodney Ave. Dear Sir: Recently a representative of this office made an inspection of the above listed premises of which I am informed you are the agent, and reports that the house is open and accessable for small boys to congregate in. As this condition constitutes a serious fire hazard you are hereby ordered to have the building securely locked. Kindly give this your immediate attention. Very truly yours Fire Marshal. HS: WF

## ASSISTANT FIRE MARSHAL'S SPECIAL COMPLAINT REPORT

	Date (Anil // 1927
Occupant Vacant House	Address 546 Poducy
Owner	Address
Agent Whefield Tries	Address 81 - 41 St
Comparint Variet Hou	ed, open, allowing
a slace for sma	el boys to congregat
smoke cigarettes + Ex	Address Address  Addr
1	
The state of the s	
*	
What changes do you recommend or	think nagaggery?
- Level V	rkept closed
**************************************	
	*
	21. N. Ping
	Assistant Fire Marshal

NOTE: This blank is to be used on all complaints on which letters are to be sent from the office.

Draw diagram on the reverse side of this blank when necessary to make information complete.

March 14, 1930.

Mr. Hugh Hume., 1034 Chamber of Commerce Bldg., City.

Re: 546 Rodney Avenue.

Dear Sir:

A representative of this office recently inspected the above listed premises, of which I am informed you are owner, and reports that the building is vacant and open, with doors and windows broken, and is being used as a rendez-vous by undesirable characters who frequent same, also, due to improper plumbing, the building has been posted for insanitary conditions by the City Health Division.

As this building in its present deteriorated condition constitutes a fire hazard and due to close proximity to school, seriously endangers same, and due also, to the fact that the building has apparently outlived its usefulness and would entail considerable expense to place same in tenantable condition, it is hereby ordered by this office that this old building be wrecked and all debris removed from the premises.

If im ediate steps are not taken to remove this menace, I will petition the City Council to condemn the building under Ordinance No. 56439, "Dangerous Buildings", which provides that the cost of wrecking same be levied against the property.

Yours very truly,

FIRE MARSHAL.

FWR:WRF CURTIS: INSP:

THE SPECTATOR Portland's Only Fine Weekly Review of PUBLIC AFFAIRS, the ARTS, SOCIETY and SPORT 1038-1040 CHAMBER OF COMMERCE BUILDING, 271 STARK STREET PORTLAND, OREGON Phone **HUGH HUME** BRoadway 4010 Mar. 15, 1930 Editor Mr. Glen W. Roberts, Fire Marshal, City Hall, ortland, Ore. My dear Fire Marshal: Your letter in regard to the house at 546 Rodney Avenue has been received, and has been sent to my agents, Wakefield, Fries & Co., who will see that your suggestions are at once complied with. Thanking you for bringing this matter to my attention, and with my very kind regards, I am yours very truly, Much Inune HH/BL

March 21, 1930.

Mr. Hugh. Hume., 1034 Chamber of Commerce Bldg., City.

Dear Sir:

This is to advise you that we have received your intention to have the old dwelling owned by you at 546 Rodney Avenue, wrecked and the debris removed, and we are writing this for the express purpose of thanking yourfor your prompt compliance with our recommendation.

Oldbuildings which are no longer a source of revenue soon become serious fire hazards as they are visited by neighborhood children and undesirable persons, and are certainly not an object of civic pride.

I am deeply appreciative of your coe operation with this office in our efforts to prevent fire and save life and property.

Respectfully yours,

FIRE MARSHAL.

FWR: WRF

August 8, 1929.

Mrs. William G. Weber.,

106 Oak St., Hood River, Oregon.

Re: 574 Rodney Avenue.

Door Madami

I am in receipt of a letter under date August Sirst, 1929, from the Metzger-Parker Realty Company, wherein they say they have notified you that the building and premises at the above address, for which I am informed you are the guardian, is open, full of rubbish, and dry grass is piled outside of house.

As these premises in their present condition constitute a serious fire hazard, you are hereby ordered to securely close windows and doors, and dispose of all dry gress and rubbish in and about premises.

Kindly give this matter your immediate attention.

Respectfully

FIRE MARSHAL.

FWR: WRF LIMINEVILLE: INOP:

## METZGER-PARKER COMPANY

REALTORS

METZGER
PARKER COMPANY
BROADWAY 5355

PORTLAND, OREGON

August 1, 1929

Capt. Lenneville
Fire Marshall's office
City Hall
Portland, Oregon

Dear Sir:

In reply to your request that we have the house at 574 Rodney Avenue cleaned up or boarded up, we wish to advise you that we would appreciate it if you would write a letter direct to Mrs. William G. Weber, guardian, 106 Oak St., Hood River, as we have previously notified Mrs. Weber that something would have to be done. We do not wish to assume responsibility of a "fire Hazzard" on the property.

Yours very truly,

METZGER-PARKER COMPANY

asurer

ı

AHP W

## ASSISTANT FIRE MARSHAL'S SPECIAL COMPLAINT REPORT

	Date	aug. 5-	192 9
		Address 374.	Backer A.
4	Missiner Mrs. Was H. Meber	Address 106 -	Pol It Houd
	Agent Metiger-Parker les.		rockey Rive
	Complaint House is war and	+ onen Ho	and in
	1010 1110	grass & ru	thish ailed
	ant sidy of louse.		
	0		
			X-F
			<u> </u>
	What changes did you recommend and	to whom?	10
	The some property	or Alone	A down.
	recan up premises	much T	mark:
		7.001	. 01
		Aleman	relle

Assistant Fire Marshal

NOTE: This blank to be used for all complaints on which notices are to be sent from office.

Draw diagram on reverse side when necessary to make information complete.

March 16, 1948

REPERENCE: File No. 37

Mr. C. W. Klippel Rt. 17, Box 1608 Milwaukie, Oregon

Doox Sir.

This office has been given to understand that you are the owner of a property at 5400 IE Rodney Avenue, Portland.

In the duplex at this address are two Vortex oil burners which are in a hazardous condition, which condition must be remedied promptly. Oil leaks from the nozzles of the burners and collects in the bottom of the combustion chamber, thereby creating a fire hazard. In fact, one did catch fire, as you probably know. On this particular model oil burner it has sometimes been necessary in the past to install an additional pump cut-out so there will be no drip after the burner shuts down. This may be necessary in this case but at any rate a responsible service man should correct the condition of these burners inmediately. Failing this, it will be necessary for this office to order the burners shut down until they have been repaired to our satisfaction.

Please give this matter your prompt attention.

Yours very truly,

M. D. Woodworth Fire Marshal

MAW j=