
UBC/6/#2 Wood frame, Rated Construction Page 17 of 29 March 1, 1999

#### INDEX OF 1-HR WOOD FRAME DETAILS

#### EXTERIOR WALL / ROOF AREA SEPARATION WALL **CONDITIONS CONDITIONS** D1 EAVE BLOCKING A1 CONVENTIONAL FRAMING $\Pi$ A2 CONVENTIONAL FRAMING D2 TOP CHORD BEARING D3 ROOF OFFSET DETAIL A3 MODIFIED BALLOON FRAMING! **D4** GABLE END A4 MODIFIED BALLOON FRAMING L D5 GABLE END A5 CRAWL SPACE A6 CRAWL SPACE D6 BOTTOM CHORD BEARING D7 BOTTOM CHORD BEARING A7 JOG IN ATTIC A8 ROOF / CEILING DETAIL $\Pi$ 1 HOUR WOOD FRAME DETAILS A9 ROOF / CEILING DETAIL $\perp$ E1 DRAFT STOPPING EXCEPTION A10 CLARIFIED TRUSS E2 DRAFT STOPPING-PARTY WALLS A11 PARAPET E3 SMALL PENETRATION DETAIL A12 WALL JUNCTION W/ EXT. WALL F4 FIRE BLK'G WALL DIAGRAM A13 JOINING WALLS E5 RECESSED ITEMS INTERIOR WALL CONDITIONS MISCELLANEOUS DETAILS **B1** CONVENTIONAL FRAMING F1 CONVENTIONAL DUCT B2 MODIFIED BALLOON FRAMING I F2 ALTERNATE DUCT B3 MODIFIED BALLOON FRAMING I B4 DIFFERING HEIGHT JOIST F3 ALTERNATE DUCT $\perp$ F4 TUB / SHOWER DETAILS **B5** CONVENTIONAL FRAMING **B6** CORRIDOR FRAMING B7 MODIFIED BALLOON FRAMING II B8 CORRIDOR DETAIL **EXTERIOR WALL CONDITIONS** C1 CONVENTIONAL FRAMING C2 CONVENTIONAL FRAMING C3 MODIFIED BALLOON FRAMING II C4 MODIFIED BALLOON FRAMING 1 C5 MODIFIED BALLOON FRAMING 1


UBC/6/#2 Wood frame, Rated Construction Page 18 of 29 March 1, 1999




UBC/6/#2 Wood frame, Rated Construction Page 19 of 29 March 1, 1999

## AREA SEPARATION WALL/ROOF CONDITIONS

ROOF / CEILING DETAIL







**UBC/6/#2 Wood frame, Rated Construction** Page 20 of 29 March 1, 1999

### AREA SEPARATION WALL / ROOF CONDITIONS


ROOF / CEILING DETAIL




UBC/6/#2 Wood frame, Rated Construction Page 21 of 29 March 1, 1999




UBC/6/#2 Wood frame, Rated Construction Page 22 of 29 March 1, 1999



UBC/6/#2 Wood frame, Rated Construction Page 23 of 29 March 1, 1999




UBC/6/#2 Wood frame, Rated Construction Page 24 of 29 March 1, 1999




UBC/6/#2 Wood frame, Rated Construction Page 25 of 29 March 1, 1999

# **EXTERIOR WALL / ROOF CONDITIONS** PRE-FABRICATED WOOD I - JOISTS BY INTERPRETATION, VENTED EAVE BLOCKING MAY BE USED, EXCEPT OVER & WITHIN 5' OF EITHER SIDE OF NON-PROTECTED OPENINGS IN FLR. BELOW (IRREGARDLESS OF HT. OF FLOOR). REFERENCE STRUCTURAL DWGS. FOR ADDITIONAL INFORMATION RATED GYP. SHT'G TRUSS W GABLE END FRAMING @ 16" O.C. D1 EAVE BLOCKING **→** DRAFTSTOP MAT'L ROOF OFFSET DETAIL TOP CHORD BEARING **D3** 5TANDARD & AT ONE HOUR WALL


UBC/6/#2 Wood frame, Rated Construction Page 26 of 29 March 1, 1999




UBC/6/#2 Wood frame, Rated Construction Page 27 of 29 March 1, 1999



UBC/6/#2 Wood frame, Rated Construction Page 28 of 29 March 1, 1999



UBC/6/#2 Wood frame, Rated Construction Page 29 of 29 March 1, 1999



TYPICAL BUILDING SECTION / DETAIL LOCATOR