# CITY OF PORTLAND, OREGON



Crive the cri

Bureau of Development Services FROM CONCEPT Services

# Staff Presentation to the **Portland Design Commission**

Land Use Review Hearing LU 15-259840 DZM BURNSIDE DELTA

> **February 4, 2016** DAR: September 10, 2015



Site Area Land Area: 10,232 SF

Site Disposition W Slope – 12'

Existing Condition Surface Parking Lot

Street Frontages E Burnside – N SE Sandy Blvd – S/E SE 11<sup>th</sup> Ave – W

# Plan Districts / Approval Criteria

Central City Plan District

Central Eastside Sub-district

Central City Fundamental / Central Eastside Design Guidelines





Site Area Land Area: 10,232 SF

Site Disposition W Slope – 12'

Existing Condition Surface Parking Lot

#### **Street Frontages**

E Burnside – N SE Sandy Blvd – S/E SE 11<sup>th</sup> Ave – W

# Plan Districts / Approval Criteria

Central City Plan District

Central Eastside Sub-district

Central City Fundamental / Central Eastside Design Guidelines





Site Area Land Area: 10,232 SF

Site Disposition W Slope – 12'

Existing Condition Surface Parking Lot

Street Frontages E Burnside – N SE Sandy Blvd – S/E SE 11<sup>th</sup> Ave – W

#### **Street Designation**

E Burnside St – City Walkway, Regional Mainstreet, Local Service Bikeway SE 11<sup>th</sup> Ave – Local Service Walkway, City Bikeway SE Sandy Blvd – City Walkway, Community Corridor, City Bikeway

#### Transit

Street Car – 6-blocks west along SE Grand Ave Bus – Frequent Service on E Burnside (transfer stop, time point, driver release), Sandy, 12<sup>th</sup> Ave





Site Area Land Area: 10,232 SF

Site Disposition W Slope – 12'

Existing Condition Surface Parking Lot

Street Frontages E Burnside – N SE Sandy Blvd – S/E SE 11<sup>th</sup> Ave – W

### CONTEXT

#### View: Context W

View: Context E

View: Context NE

View: Context N





#### CONTEXT

View: Context W

#### View: Context E

View: Context NE

View: Context N


# The **SITE**

Site Area Land Area: 10,232 SF

Site Disposition W Slope - 12'

Existing Condition Surface Parking Lot

Street Frontages E Burnside – N SE Sandy Blvd – S/E SE 11<sup>th</sup> Ave – W





Site Area Land Area: 10,232 SF

Site Disposition W Slope – 12'

Existing Condition Surface Parking Lot

Street Frontages E Burnside – N SE Sandy Blvd – S/E SE 11<sup>th</sup> Ave – W

#### CONTEXT

View: Context W

View: Context E

View: Context NE

View: Context N





Site Area Land Area: 10,232 SF

Site Disposition W Slope - 12'

Existing Condition Surface Parking Lot

Street Frontages E Burnside – N SE Sandy Blvd – S/E SE 11<sup>th</sup> Ave – W




View: Context W

View: Context E

View: Context NE

View: Context N






# EXd, Central Employment


w/ Design Overlay





Base FAR	3:1
Max Bonus	3:1 +
Max FAR	6:1





Base Height	50'
Max Bonus	45' +
Max Height	95'





# The **PROJECT OVERVIEW**

#### 5 over 1: Residential/Retail

60,600 GSF 57,587 NSF 84 Apartments 2,150 SF Retail – NW & NE Parking – 22 auto 126 long-term bike 0 short-term bike


# Height

6 Floors 77' to Top-of-Parapet

FAR

5.7:1 proposed







# **ISSUE #1:** Guideline 5-1 *Reinforce Arcade*

**ISSUE #2:** Guideline C2 *Quality and Permanence* 

**ISSUE #3:** Guideline C5 *Coherency* 

**ISSUE #4:** Guideline C10 Integrate Encroachments

**ISSUE #5:** Modification 1 *Parking Area Layouts* 


# ARCADE

The proposal includes canopies and balconies instead of an arcade or similar encroachment (Sheet C11).

## *?*: What form of expression meets Guideline A5-1:

*"Maintain, continue and reinforce the effect of sidewalk arcaded buildings fronting on East Burnside Street."* 





**ISSUE #1:** Guideline 5-1 *Reinforce Arcade* 

### **ISSUE #2:** Guideline C2 *Quality and Permanence*

**ISSUE #3:** Guideline C5 *Coherency* 


**ISSUE #4:** Guideline C10 Integrate Encroachments

**ISSUE #5:** Modification 1 *Parking Area Layouts* 

# **METAL PANELS**

Because no details or materials samples have been submitted depicting the cladding assembly for the flush-seam metal panel, Staff is unable to determine whether the proposed cladding promotes quality and permanence.





**ISSUE #1:** Guideline 5-1 *Reinforce Arcade* 

**ISSUE #2:** Guideline C2 *Quality and Permanence* 

#### **ISSUE #3:** Guideline C5 *Coherency*

**ISSUE #4:** Guideline C10 Integrate Encroachments

**ISSUE #5:** Modification 1 *Parking Area Layouts* 

## TREAD PLATE STEEL SAMPLE

Because the proposed application of tread plate steel is a significant departure from convention, it is essential that renderings be provided accurately conveying the appearance of the tread plate material as detailed. Because the renderings submitted by the Applicant do not clearly depict the material, a wall mock-up shall be presented at the hearing. Until the mock-up is reviewed by Staff and the Commission, it is not possible to determine if the proposed tread plate steel will result in a coherent composition.





**ISSUE #1:** Guideline 5-1 *Reinforce Arcade* 

**ISSUE #2:** Guideline C2 *Quality and Permanence* 

**ISSUE #3:** Guideline C5 *Coherency* 


### **ISSUE #4:** Guideline C10 Integrate Encroachments

**ISSUE #5:** Modification 1 *Parking Area Layouts* 

# **Proposed Condition**

Because Guideline C10 is intended to enhance priority pedestrian environments abutting the project site – in this case, the E Burnside frontage and not the SE 11th Ave frontage – any proposed encroachment ought to firstly be oriented toward E Burnside and secondly to other abutting streets. Were some amount of encroachment (6' to 8' per finding A5-1 above) to be oriented toward E Burnside, additional encroachment could be approved for SE 11th Ave.





**ISSUE #1:** Guideline 5-1 *Reinforce Arcade* 

**ISSUE #2:** Guideline C2 *Quality and Permanence* 

**ISSUE #3:** Guideline C5 *Coherency* 

**ISSUE #4:** Guideline C10 Integrate Encroachments

**ISSUE #5:** Modification 1 *Parking Area Layouts* 

# **Proposed Condition**

Parking areas shall be designed so that a vehicle may enter or exit without having to move another vehicle. PBOT has indicated that prior to supporting this Modification, a Queuing Analysis shall be submitted. At the time of the publication of this Staff Report, no such analysis had been submitted. As such, Staff cannot determine that the parking layout as proposed will better meet Guideline C1-1.





# **Staff Recommendation**

As outlined in the Staff Report:

#### **DESIGN REVIEW DENIAL**

7-Story market rate housing project citing findings that the project as proposed does not comply all Approval Criteria.





# questions

