# Safety Data Sheet DURA-WELD FC

Supercedes Date 07/12/2013

Issuing Date 01/26/2017

### 1. PRODUCT AND COMPANY IDENTIFICATION

Product Name DURA-WELD FC Recommended use Welding Information on Manufacturer X-ERGON by Partsmaster, Div of NCH Corp.

P.O. Box 655326 Dallas, TX 75265-5326 Product Code 66040035 Chemical nature Inorganic solid blend Emergency Telephone Number CHEMTREC<sup>®</sup> 800-424-9300 Telephone inquiry 800-336-0450

# 2. HAZARD IDENTIFICATION

Color Dark gray Physical state Solid Odor Odorless

Mixture or Pure Substance: Mixture

This Safety Data Sheet (SDS) was prepared in accordance with OSHA 2012 - 29 CFR 1910.1200, "Hazard Communication".

#### **GHS**

#### Classification

Physical Hazards

#### Health Hazard

Acute Oral Toxicity

Skin Corrosion/Irritation

Serious Eye Damage/Eye Irritation

Skin sensitization

Category 2

Skin sensitization

Carcinogenicity

Carcinogenicity

Specific target organ toxicity (repeated exposure)

Category 1

Category 1

Category 1

#### Other hazards

Arc Rays can injure and burn eyes and skin Electric shock can kill FUMES AND GASES can be hazardous to your health.

#### Labeling Signal Word DANGER



### Hazard statements

H319 - Causes serious eye irritation

H315 - Causes skin irritation

H302 - Harmful if swallowed

H317 - May cause an allergic skin reaction

H350 - May cause cancer

H372 - Causes damage to organs through prolonged or repeated exposure

### Precautionary Statements

P201 - Obtain special instructions before use

P202 - Do not handle until all safety precautions have been read and understood

P260 - Do not breathe dust or fume.

P270 - Do not eat, drink or smoke when using this product.

P281 - Use personal protective equipment as required

 $\ensuremath{\mathsf{P280}}$  - Wear protective gloves, protective clothing and eye protection.

P264 - Wash face, hands and any exposed skin thoroughly after handling.

P272 - Contaminated work clothing should not be allowed out of the workplace

P308 + P313 - IF exposed or concerned, get medical attention

P301+ P312 - IF SWALLOWED: Call a physician if unwell

P330 - Rinse mouth

P302 + P352 - IF ON SKIN: Wash with plenty of soap and water

P333 + P313 - If skin irritation or rash occurs, get medical attention

P362 - Take off contaminated clothing and wash before reuse.

P305 + P351 + P338 - IF IN EYES: Rinse cautiously with water for several minutes.

Remove contact lenses, if present and easy to do. Continue rinsing.

P337 + P313 - If eye irritation persists, get medical attention.

P501 - Dispose of contents and container in accordance with applicable local regulations.

3. COMPOSITION / INFORMATION ON INGREDIENTS					
Component	CAS No.	Weight %			
Iron	7439-89-6	75-98			
Titanium dioxide	13463-67-7	5-10			
Manganese	7439-96-5	1-5			
Silicon	7440-21-3	1-5			
Quartz	14808-60-7	.1-1.5			
Calcium carbonate	1317-65-3	.5-1.5			
Molybdenum	7439-98-7	.1-1			
Zirconium oxide	1314-23-4	.5-1			
Potassium oxide	12136-45-7	.5-1			
Nickel	7440-02-0	0.5-4			
Magnesium	7439-95-4	.5-1			
Calcium Fluoride	7789-75-5	0-2			
Aluminum	7429-90-5	.1-1			
Copper	7440-50-8	0-1			

<sup>\*</sup>The exact percentage (concentration) of composition has been withheld as a trade secret

### 4. FIRST AID MEASURES

General advice Avoid contact with skin, eyes and clothing. Avoid breathing dust.

Eye Contact Rinse immediately with plenty of water, also under the eyelids, for at least 15 minutes. If symptoms

persist, call a physician.

Skin Contact In case of contact, immediately flush skin with soap and plenty of water. If skin irritation persists, call

a physician.

InhalationRemove person to fresh air. If signs/symptoms continue, get medical attention.IngestionIf swallowed, do not induce vomiting - seek medical advice. Rinse mouth.

Notes to physician Treat symptomatically.

# 5. FIRE-FIGHTING MEASURES

Flash Point The product is not flammable Method No data available Upper: No data available Lower: No data available

Suitable Extinguishing Media

Carbon dioxide (CO2). Dry chemical. Foam. Water spray.

**Specific hazards arising from the chemical** Dust can form an explosive mixture in air.

**Protective Equipment and Precautions for Firefighters** 

As in any fire, wear self-contained breathing apparatus pressure-demand, NOHSC (approved or equivalent) and full protective gear.

 NFPA
 Health 2
 Flammability 0
 Instability 0

 HMIS
 Health 2
 Flammability 0
 Instability 0

#### 6. ACCIDENTAL RELEASE MEASURES

Personal Precautions Use personal protective equipment. Prevent further leakage or spillage if safe to do so. Material can

create slippery conditions.

**Environmental Precautions**Do not flush into surface water or sanitary sewer system.

Methods for Containment Contain spillage, soak up with non-combustible absorbent material, (e.g. sand, earth,

diatomaceous earth, vermiculite) and transfer to a container for disposal according to local / national

regulations (see section 13).

Methods for Cleaning Up Contain spillage, soak up with non-combustible absorbent material, (e.g. sand, earth,

diatomaceous earth, vermiculite) and transfer to a container for disposal according to local / national

regulations (see section 13).

Neutralizing Agent Not applicable.

# 7. HANDLING AND STORAGE

Handling
Avoid contact with skin, eyes and clothing. Do not eat, drink or smoke when using this product.

Storage
Storage Temperature
Storage Conditions
Avoid contact with skin, eyes and clothing. Do not eat, drink or smoke when using this product.

Store in original container. Keep containers tightly closed in a dry, cool and well-ventilated place.

Minimum
No information available
Maximum
No information available
Indoor
X
Outdoor
Heated
Refrigerated

### 8. EXPOSURE CONTROLS / PERSONAL PROTECTION

**Exposure Guidelines** 

Component	ACGIH TLV	OSHA PEL	NIOSH
Titanium dioxide	TWA: 10 mg/m <sup>3</sup>	TWA: 15 mg/m <sup>3</sup> total dust	5000 mg/m <sup>3</sup>
Manganese	TWA: 0.02 mg/m <sup>3</sup> respirable fraction	Ceiling: 5 mg/m <sup>3</sup>	500 mg/m <sup>3</sup>
	TWA: 0.1 mg/m <sup>3</sup> inhalable fraction		STEL 3 mg/m <sup>3</sup>
	TWA: 0.02 mg/m <sup>3</sup>		TWA: 1 mg/m <sup>3</sup> fume TWA: 1 mg/m <sup>3</sup>
	TWA: 0.1 mg/m <sup>3</sup>		
Silicon	No data available	TWA: 15 mg/m <sup>3</sup> total dust	TWA: 10 mg/m <sup>3</sup> total dust
		TWA: 5 mg/m <sup>3</sup> respirable fraction	TWA: 5 mg/m <sup>3</sup> respirable dust
Quartz	TWA: 0.025 mg/m <sup>3</sup> respirable	No data available	50 mg/m <sup>3</sup> respirable dust
	fraction		TWA: 0.05 mg/m <sup>3</sup> respirable dust
Calcium carbonate	No data available	TWA: 15 mg/m <sup>3</sup> total dust	TWA: 10 mg/m <sup>3</sup> total dust
		TWA: 5 mg/m <sup>3</sup> respirable fraction	TWA: 5 mg/m <sup>3</sup> respirable dust
Molybdenum	TWA: 10 mg/m <sup>3</sup> inhalable fraction	No data available	5000 mg/m <sup>3</sup>
	TWA: 3 mg/m <sup>3</sup> respirable fraction		
Zirconium oxide	TWA: 5 mg/m <sup>3</sup>	TWA: 5 mg/m <sup>3</sup>	STEL 10 mg/m <sup>3</sup>
			TWA: 5 mg/m <sup>3</sup>
Nickel	TWA: 1.5 mg/m <sup>3</sup>	TWA: 1 mg/m <sup>3</sup>	10 mg/m <sup>3</sup>
			TWA: 0.015 mg/m <sup>3</sup>
Calcium Fluoride	TWA: 2.5 mg/m <sup>3</sup>	TWA: 2.5 mg/m <sup>3</sup>	No data available
		TWA: 2.5 mg/m <sup>3</sup> dust	
Aluminum	TWA: 1 mg/m <sup>3</sup> respirable fraction	TWA: 15 mg/m <sup>3</sup> total dust	TWA: 10 mg/m <sup>3</sup> total dust
		TWA: 5 mg/m <sup>3</sup> respirable fraction	TWA: 5 mg/m <sup>3</sup> respirable dust TWA:
			5 mg/m <sup>3</sup>
Copper	TWA: 0.2 mg/m <sup>3</sup> fume TWA: 1 mg/m <sup>3</sup>	TWA: 0.1 mg/m <sup>3</sup> fume	100 mg/m <sup>3</sup> dust, fume and mist
	dust and mist	TWA: 1 mg/m <sup>3</sup> dust and mist	TWA: 1 mg/m <sup>3</sup> dust and mist
			TWA: 0.1 mg/m <sup>3</sup> fume
Fraincering Macoures	Llas anaugh vantilation lassl subs		

**Engineering Measures** 

Use enough ventilation, local exhaust at the arc, or both to keep the fumes and gases below the TLV's in the worker's breathing zone and in the general area. Train the worker to keep his head out of the fumes.

Personal Protective Equipment Eye/Face Protection

Wear a helmet or use face shield with filter lens of appropriate shade number (SEE ANSI/ASCZ49.1) provide protective screen and flash goggles, if necessary, to shield others. As a rule of thumb, start a shade that is too dark to see the weld zone. Then go next lighter shade which gives sufficient view of the weld zone.

Skin Protection Respiratory Protection Welder's leather gloves, Wear fire/flame resistant/retardant clothing.

Use enough ventilation, local exhaust at the arc, or both to keep the fumes and gasses below the TLV's in the workers' breathing zone and the general area. Train the worker to keep his head out of the fumes. Use MSHA/NIOSH approved or equivalent fume respirator or air supplied respirator when welding in a confined space or when local exhaust or ventilation does not keep exposure below

**General Hygiene Considerations** 

Do not eat, drink or smoke when using this product. Avoid contact with skin, eyes and clothing. Wear head and body protection which help to prevent injury from radiation, sparks, and electrical shock. See ANSI Z49.1. At minimum, this includes welder's gloves and a protective face shield, and may include arm protectors, aprons, hat, shoulder protection as well as dark nonsynthetic clothing. Train the welder not to touch live electrical parts and to insulate himself from work and ground.

### 9. PHYSICAL AND CHEMICAL PROPERTIES

Physical stateSolidViscosityNot applicableColorDark grayOdorOdorless

**Odor Threshold** Not applicable Textured black paste **Appearance** pН Not applicable Specific Gravity No data available **Evaporation Rate** Percent Volatile (Volume) Not applicable No information available VOC Content (%) Vapor Pressure No information available. Not applicable

Vapor DensityNot applicableSolubilityInsolublen-Octanol/Water PartitionNo data availableMelting Point/Range1800 °F / 982 °CDecomposition TemperatureNo data availableBoiling Point/RangeNo data available °F / °C

Flammability (solid, gas)

No data available

The product is not flammable

Method

No data available

Autoignition Temperature No information available.

Upper: No data available Lower: No data available

# 10. STABILITY AND REACTIVITY

**Chemical Stability** 

Conditions to Avoid Incompatible Products Decomposition Temperature Hazardous Decomposition Products Stable under normal conditions. Hazardous polymerization does not

occur.

Keep away from open flames, hot surfaces, and sources of ignition.

Incompatible with oxidizing agents, Strong acids.

No data available

Fumes and gasses produced by welding, brazing and similar processes cannot be classified simply. The composition and quantity of both are dependent upon the metal being welded, the process, the procedures and the filler metal being used. Other conditions which also influence the composition and quantity of fumes and gases to which the worker may be exposed include: coatings on the metal being welded, the number of welders and the volume of the work space, the quality and amount of ventilation used, the position of the welder's head in relation to the fume plume, as well as the presence of contaminants in the atmosphere when the filler metal is consumed. The fume and gas decomposition products generated are different in percent and form the product ingredients listed in Section III. The products formed in normal operation include those originating from the volatilization, reaction and oxidation of the filler metal, the metal being welded, the coatings, etc. as noted above. One recommended way to determine the composition and quality of fumes and gases to which workers are exposed is to take an air sample inside the welders helmet if worn or in the workers breathing zone. See ANSI/AWS F1.1 "Method For Sampling Airborne Particles Generated By Welding And Allied Processes" available from the American Welding Society, P.O. Box 35140, Miami, FL 33135.

Possibility of Hazardous Reactions

None under normal processing.

#### 11. TOXICOLOGICAL INFORMATION

Product Information Generally established for welding fumes at 5mg/m<sup>3</sup>. May be lower for some constituents

The following values are calculated based on chapter 3.1 of the GHS document

Oral LD50 No information available
Permal LD50 No information available

Inhalation LC50

GasNo information availableMistNo information availableVaporNo information available

Principle Route of Exposure Primary Routes of Entry

Acute Effects:

Ingestion

Inhalation, Ingestion.

Skin contact.

**Eyes** Causes eye irritation. Welding arc may damage eyes.

Skin Causes skin irritation. Repeated or prolonged skin contact may cause allergic reactions with

susceptible persons. May cause allergic skin reaction.

Inhalation Welding fumes may result in discomfort such as: dizziness, nausea, or dryness or irritation of nose,

throat, or eyes. Fumes can aggravate asthma, bronchial conditions, or allergies. Individuals with allergies or impaired respiratory function may have symptoms worsen by exposure to welding fumes. Excessive inhalation of iron oxides fumes or dust can lead to irritation of the respiratory tract. Inhalation may cause central nervous system effects. Symptoms and signs include headache, dizziness, fatigue, muscular weakness, drowsiness and in extreme cases, loss of consciousness. May be harmful if swallowed. Ingestion may cause gastrointestinal irritation, nausea, vomiting and

diarrhea.

Chronic Toxicity Long term. Inhalation of dust may cause shortness of breath, tightness of the chest, a sore throat

and cough. Inhalation of manganese fumes may affect the central nervous system, may cause spastic gait, drowsiness, paralysis and other neurological problems with symptoms including weakness and tremors resembling Parkinson's disease. Behavioral changes and changes in handwriting may also appear. The TLV for Manganese (0.02 mg/m³) will be reached before the

general limit for welding fumes of 5mg/m<sup>3</sup> is reached. Monitor fumes for manganese

levels. Repetitive exposure to nickel oxides may lead to lung fibrosis or pneumoconiosis. Soreness and itchiness of the nose and changes in skin color and/or appearance may also result. Nickel compounds are on the IARC list as posing a carcinogenic risk to humans. OSHA (29 CFR 1910.120) lists nickel as possible carcinogen. Fume may cause Wilson's disease in some individuals with a rare inherited metabolic disorder characterized by retention of copper in the liver, brain, kidney and corneas. Wilson's disease, if untreated can result in liver failure. Inhalation of Molybdenum fumes has caused kidney damage, respiratory irritation and liver damage in animals.

Respiratory system, Central nervous system, Kidney, Skin, Blood, Liver.

Pre-existing respiratory and skin conditions such as asthma, emphysema, and dermatitis, Central

Target Organ Effects

Aggravated Medical Conditions

nervous system, Kidney disorders, Allergies, Skin disorders, Liver disorders.

Component Information

ACULE I UXICILY	Acute	Toxicity
-----------------	-------	----------

Component	Oral LD50	Dermal LD50	Inhalation LC50	Draize Test	Other
Iron 7439-89-6	= 984 mg/kg ( Rat )	no data available	No data available	No data available	No data available
Titanium dioxide 13463-67-7	> 10000 mg/kg ( Rat )	no data available	No data available	No data available	No data available
Quartz 14808-60-7	= 500 mg/kg ( Rat )	no data available	No data available	No data available	No data available
Calcium carbonate 1317-65-3	6450 mg/kg ( Rat )	no data available	no data available	No data available	No data available
Nickel 7440-02-0	> 9000 mg/kg ( Rat )	no data available	No data available	No data available	No data available
Magnesium 7439-95-4	= 230 mg/kg ( Rat )	no data available	No data available	No data available	No data available
Calcium Fluoride 7789-75-5	= 4250 mg/kg ( Rat )	no data available	No data available	No data available	No data available

Component	Mutagenicity	Sensitization	Developmental Toxicity	Reproductive Toxicity	Target Organ Effects
Titanium dioxide 13463-67-7	No data available	No data available	No data available	No data available	Respiratory system
Manganese 7439-96-5	No data available	No data available	No data available	No data available	Blood; Central nervous system; Respiratory system; Kidney
Silicon 7440-21-3	No data available	No data available	No data available	No data available	Skin; Eyes; Respiratory system
Quartz 14808-60-7	No data available	No data available	No data available	No data available	Eyes; Respiratory system
Calcium carbonate 1317-65-3	No data available	No data available	No data available	No data available	Skin; Eyes; Respiratory system
Molybdenum 7439-98-7	No data available	No data available	No data available	No data available	Eyes; Respiratory system; Liver; Kidney
Zirconium oxide 1314-23-4	No data available	No data available	No data available	No data available	Skin; Respiratory system
Nickel 7440-02-0	No data available	No data available	No data available	No data available	Lungs; Nasal Cavities; Skin
Aluminum 7429-90-5	No data available	No data available	No data available	No data available	Skin; Eyes; Respiratory system
Copper 7440-50-8	No data available	No data available	No data available	No data available	Skin; Eyes; Respiratory system; Liver; Kidney

Carcinogenicity

The table below indicates whether each agency has listed any ingredient as a carcinogen.

Component	ACGIH	IARC	NTP	OSHA	Other
Titanium dioxide	not applicable	Group 2B	not applicable	X	not applicable
13463-67-7					
Quartz	A2	Group 1	Known	Х	not applicable
14808-60-7					
Nickel	not applicable	Group 2B	Known	X	not applicable
7440-02-0			Reasonably Anticipated		

# 12. ECOLOGICAL INFORMATION

Product Information Component Information No information available.

Component	Toxicity to Algae	Toxicity to Fish	Microtox	Crustacea	Partition coefficier
Nickel	EC50 = 0.18 mg/L Pseudokirchneriella subcapitata 72 h EC50 0.174 - 0.311 mg/L	LC50 > 100 mg/L Brachydanio rerio 96 h LC50 = 1.3 mg/L Cyprinus carpio 96 h		100: 48 h Daphnia magna mg/L EC50 1: 48 h Daphnia magna mg/L EC50 Static	N/A
	Pseudokirchneriella subcapitata 96 h	LC50 = 10.4 mg/L Cyprinus carpio 96 h		Ü	
Copper	EC50 0.0426 - 0.0535 mg/L Pseudokirchneriella subcapitata 72 h EC50 0.031 - 0.054 mg/L Pseudokirchneriella subcapitata 96 h	LC50 0.0068 - 0.0156 mg/L Pimephales promelas 96 h LC50 < 0.3 mg/L Pimephales promelas 96 h LC50 = 0.2 mg/L Pimephales promelas 96 h LC50 = 0.052 mg/L Oncorhynchus mykiss 96 h LC50 = 1.25 mg/L Lepomis	No information available	0.03: 48 h Daphnia magna mg/L EC50 Static	N/A

macrochirus 96 h	
LC50 = 0.3 mg/L Cyprinus carpio 96	
h   h	
LC50 = 0.8 mg/L Cyprinus carpio 96	
h   h	
LC50 = 0.112 mg/L Poecilia reticulata	
96 h	

Persistence and Degradability
Bioaccumulation
No information available.
No information available.
No information available.

# 13. DISPOSAL CONSIDERATIONS

Product Disposal Dispose of in accordance with local regulations.

Container Disposal Empty containers should be taken for local recycling, recovery, or waste disposal.

#### 14. TRANSPORT INFORMATION

DOT Not regulated

TDG Not regulated

ICAO Not regulated

IATA Not regulated

IMDG/IMO Not regulated

### 15. REGULATORY INFORMATION

Inventories

TSCA Complies
DSL Complies

### **U.S. Federal Regulations**

#### **SARA 313**

Section 313 of Title III of the Superfund Amendments and Reauthorization Act of 1986 (SARA). This product contains a chemical or chemicals which are subject to the reporting requirements of the Act and Title 40 of the Code of Federal Regulations, Part 372:

# SARA 311/312 Hazardous Categorization

Acute Health Ha	zard Chronic Healt	h Hazard Fire H	azard Sudden Rele	ase of Reactive Hazard
			Pressure Ha	azard
Yes	No	N	o No	No

#### CERCLA None

Component	Hazardous Substances RQs	CERCLA EHS RQs
Nickel	100 lb	Not applicable
Copper	5000 lb	Not applicable

# U.S. State Regulations

 California Proposition 65
 This product contains the following Proposition 65 chemicals:

Component	CAS No.	California Prop. 65
Quartz	14808-60-7	carcinogen
Nickel	7440-02-0	carcinogen

### 16. OTHER INFORMATION

Prepared By Christopher Drogin
Supercedes Date 07/12/2013
Issuing Date 01/26/2017

Reason for RevisionNo information available.GlossaryNo information available.List of References.No information available.

X-ERGON by Partsmaster, Div of NCH Corp.assumes no responsibility for personal injury or property damage caused by the use, storage, or disposal of the product in a manner not recommended on the product label. Users assume all risks associated with such unrecommended use, storage or disposal of the product. The information provided on this document is correct to the best of our

knowledge, information and belief at the date of its publication. The information given is designed only as a guide for safe handling, use, processing, storage, transportation, disposal and release and is not to be considered as a warranty or quality specification. The information relates only to the specific material designated and may not be valid for such material used in combination with any other material or in any process, unless specified in the text.