


# **Sam Jackson Park Road**

**Landslide Mitigation**

**July – August 2011**



# Crack in SJP Roadway




# 2006 Roadway View – slight crack




# 2011 Roadway View – significant crack



# Landslide Slip Failure





**Soil  
Movement  
Below  
Roadway:**


**November**

**December**

**February**

**April**

**Half Inch  
movement in  
Spring 2011**



# Detour Plan


# **Sam Jackson Park Road**

## **Landslide Mitigation**

**July 11 – August 31, 2011**







**Soil Lateral  
Movement**

**Nov – April 2011**