



**Reservoirs 6 and 2, July 1916.  
Reservoir 2, in the Background, Was Sold Off for Private Development in the 1980s.**



### Reservoirs 5 and 6

The Reservoirs — in Their Historic Condition — are Central to the Views in Mt. Tabor Park





### Reservoir 5

The Reservoirs — in Their Historic Condition — are Integral to the Experience of Mt. Tabor Park





**Hands Around the Reservoirs, 2003**  
**A Thousand Portlanders Turn Out to Show Support for Their Historic Reservoirs**  
**Reservoir 6, Sunday, September 28th, 2003**





**A Decade Later: Hands Around the Reservoirs, 2012  
Portlanders Again Rally in Support of Their Historic Reservoirs  
Reservoir 6, Sunday, October 28th, 2012**





Reservoir 6





Reservoir 6





**Reservoir 6 is Popular with Walkers and Joggers**





### **Reservoir 6: Water? Or No Water?**

**The Historic Character of the Reservoirs Would be Destroyed by Allowing Them to be Left Empty**





### **Reservoir 5 is Also Popular with Walkers**

**Joggers, Though, Not so Much, Since the Sidewalk is in Serious Disrepair — Broken, Uneven, Treacherous**





## Reservoir 5

The Park and the Reservoirs Were Designed Together a Century Ago, with Careful Attention to the Views






Reservoir 5





Reservoir 5





Reservoir 5





Reservoir 5





Reservoir 5





**Reservoir 5**  
**Water? Or No Water?**





**Reservoir 1**  
**Restored Gatehouse, Crumbling Reservoir Walls**





## Reservoir 1

Decades of Willful Neglect by the Portland Water Bureau Have Taken Their Toll





Reservoir 1





**Reservoir 1**  
**Exposed and Rusting Rebar Speeds Decay of the Concrete Walls**





**Public Drinking Fountain at Reservoir 1  
Beautiful Design, 1894  
Unconscionable State of Disrepair, 2014**





**Yet Another Rally for the Reservoirs – Friday, July 12, 2013**

**Please Act to Preserve the Integrity of These Historic Structures for the Generations to Come**