



Beautiful Mt. Tabor Park and the historic Mt. Tabor Park reservoirs offer iconic Portland views.



Carefully crafted decorative concrete designs are being allowed to crumble.



Allowing rebar to be exposed to the elements is the kiss of death for a historic asset.



Non-historical electrical conduit has been thoughtlessly inserted, and then left unattended.



A unique and historically significant drinking fountain is lost in weeds and disrepair.

